

PULL TO ACTIVATE


TO TEST: PRESS & HOLD
UNTIL TONE, THEN RELEASE



STFS/PLUS S

USER MANUAL AVAILABLE
AT STFS.COM

FCC ID: 2APRL-STFS001



ALERTS

3 TONES:
WARNING/FIRE

2 TONES:
FAULT

1 TONE:
LOW BATTERY

See Manual for full details

Manufactured in Fort Worth, TX USA
by WilliamsRDM, Inc.

