



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 20:36:17

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 20:37:22

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.JUN.2022 15:24:46

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.JUN.2022 15:25:24

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 15:25:52

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 15:26:30

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 15:26:54

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 15:27:18

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 19.JUN.2022 15:27:36

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 19.JUN.2022 15:28:11

Band 2_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 15:28:32

Band 2_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 15:28:51

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 15:29:21

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 15:29:52

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 19.JUN.2022 15:30:17

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 19.JUN.2022 15:30:45

Band 2_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 15:31:06

Band 2_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 15:31:29

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 15:32:03

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 15:32:33

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 19.JUN.2022 15:33:00

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 19.JUN.2022 15:33:33

Band 2_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 15:34:08

Band 2_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 15:34:42

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 15:35:08

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 15:35:49

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 19.JUN.2022 15:36:18

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 19.JUN.2022 15:36:50

Band 2_15 MHz_High_QPSK_RB75#0




Date: 19.JUN.2022 15:37:30

Band 2_15 MHz_High_16QAM_RB75#0




Date: 19.JUN.2022 15:38:11

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 15:38:41

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 15:39:18

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 19.JUN.2022 15:39:58

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 19.JUN.2022 15:40:44

Band 2_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 15:41:21

Band 2_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 15:41:58

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 20:40:34

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 20:39:05

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.JUN.2022 15:44:10

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.JUN.2022 15:44:49

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 15:45:19

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 15:45:58

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 15:46:25

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 15:46:46

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 19.JUN.2022 15:47:05

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 19.JUN.2022 15:47:36

Band 4_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 15:48:06

Band 4_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 15:49:01

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 15:49:25

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 15:50:02

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 19.JUN.2022 15:50:21

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 19.JUN.2022 15:50:55

Band 4_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 15:51:25

Band 4_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 15:51:49

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 15:52:17

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 15:52:47

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 19.JUN.2022 15:53:25

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 19.JUN.2022 15:54:03

Band 4_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 15:54:33

Band 4_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 15:55:06

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 15:55:47

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 15:56:22

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 19.JUN.2022 15:57:02

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 19.JUN.2022 15:57:39

Band 4_15 MHz_High_QPSK_RB75#0



Date: 19.JUN.2022 15:58:26

Band 4_15 MHz_High_16QAM_RB75#0



Date: 19.JUN.2022 15:59:03