



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 20:42:50

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 20:43:43

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 18:45:04

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 18:45:43

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 18:46:06

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 18:46:30

Band 2_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 18:46:53

Band 2_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 18:47:10

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 21:10:49

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 20:46:00

Band 2_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 20:46:53

Band 2_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 20:47:49

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 18:49:26

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 18:49:54

Band 2_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 18:50:23

Band 2_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 18:50:52

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 18:51:26

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 20:49:56


Band 2_15 MHz_High_QPSK_RB75#0



Band 2_15 MHz_High_16QAM_RB75#0




Band 2_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 18:53:52

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 18:54:32

Band 2_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 18:55:07

Band 2_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 18:55:41

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 20:51:28

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 20:51:59

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 18:58:08

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 18:58:36

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 18:58:57

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 18:59:17

Band 4_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 20:53:32

Band 4_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 19:00:01

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 20:55:53

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 20:54:55

Band 4_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 20:56:42

Band 4_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 20:57:09

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 19:02:06

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 19:02:37

Band 4_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 19:03:04

Band 4_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 19:03:30

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 19:04:04

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 19:04:41

Band 4_15 MHz_High_QPSK_RB75#0




Date: 19.JUN.2022 19:05:10

Band 4_15 MHz_High_16QAM_RB75#0




Date: 19.JUN.2022 19:05:47

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 19:06:25

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 19:07:00

Band 4_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 19:07:31

Band 4_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 19:08:14

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 20:58:39

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 20:59:21

Band 7_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 21:00:17

Band 7_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 21:00:47

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 19:10:25

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 19:10:57

Band 7_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 19:11:26

Band 7_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 19:11:58

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 19:12:48

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 21:01:53

Band 7_15 MHz_High_QPSK_RB75#0




Date: 19.JUN.2022 19:13:56

Band 7_15 MHz_High_16QAM_RB75#0




Date: 19.JUN.2022 19:14:26

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 19:15:01

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 19:16:01

Band 7_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 19:16:33

Band 7_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 19:17:11

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 19:17:52

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 19:18:34

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 19:19:33

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 19:20:05

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 21:03:14

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 19:21:22

Band 12_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 21:04:07

Band 12_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 19:22:07

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 21:05:11

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 21:05:42

Band 12_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 21:06:42

Band 12_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 21:07:15

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 19:24:11

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 19:24:43

Band 12_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 19:25:21

Band 12_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 19:25:55

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 21:08:14

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 21:08:42


Band 17_5 MHz_High_QPSK_RB25#0



Band 17_5 MHz_High_16QAM_RB25#0




Band 17_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 19:27:52

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 19:28:21

Band 17_10 MHz_High_QPSK_RB50#0



Date: 19.JUN.2022 19:28:52

Band 17_10 MHz_High_16QAM_RB50#0



Date: 19.JUN.2022 19:29:22