



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 24.DEC.2021 17:32:06

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 24.DEC.2021 17:32:20

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 10.JAN.2022 20:46:18

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 10.JAN.2022 20:47:02

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 24.DEC.2021 17:33:04

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 24.DEC.2021 17:33:21

Band 2_3 MHz_High_QPSK_RB15#0




Date: 24.DEC.2021 17:33:32

Band 2_3 MHz_High_16QAM_RB15#0




Date: 24.DEC.2021 17:33:46

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 10.JAN.2022 20:48:45

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 10.JAN.2022 20:49:07

Band 2_5 MHz_High_QPSK_RB25#0




Date: 10.JAN.2022 20:50:02

Band 2_5 MHz_High_16QAM_RB25#0




Date: 10.JAN.2022 20:50:51

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 24.DEC.2021 17:35:10

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 24.DEC.2021 17:35:34

Band 2_10 MHz_High_QPSK_RB50#0




Date: 24.DEC.2021 17:35:53

Band 2_10 MHz_High_16QAM_RB50#0




Date: 24.DEC.2021 17:36:17

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 24.DEC.2021 17:36:40

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 24.DEC.2021 17:37:03

Band 2_15 MHz_High_QPSK_RB75#0




Date: 10.JAN.2022 20:52:36

Band 2_15 MHz_High_16QAM_RB75#0




Date: 24.DEC.2021 17:38:10

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 24.DEC.2021 17:38:38

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 24.DEC.2021 17:39:05

Band 2_20 MHz_High_QPSK_RB100#0




Date: 24.DEC.2021 17:39:35

Band 2_20 MHz_High_16QAM_RB100#0




Date: 24.DEC.2021 17:40:11

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 24.DEC.2021 17:40:24

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 24.DEC.2021 17:40:38

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 24.DEC.2021 17:40:52

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 24.DEC.2021 17:41:09

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 24.DEC.2021 17:41:28

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 24.DEC.2021 17:41:45

Band 4_3 MHz_High_QPSK_RB15#0




Date: 24.DEC.2021 17:41:59

Band 4_3 MHz_High_16QAM_RB15#0




Date: 24.DEC.2021 17:42:13

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 10.JAN.2022 20:55:59

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 10.JAN.2022 20:56:29

Band 4_5 MHz_High_QPSK_RB25#0




Date: 10.JAN.2022 20:57:19

Band 4_5 MHz_High_16QAM_RB25#0




Date: 10.JAN.2022 20:57:47

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 24.DEC.2021 17:43:53

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 24.DEC.2021 17:44:18

Band 4_10 MHz_High_QPSK_RB50#0




Date: 24.DEC.2021 17:44:43

Band 4_10 MHz_High_16QAM_RB50#0




Date: 24.DEC.2021 17:45:07

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 24.DEC.2021 17:45:29

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 24.DEC.2021 17:46:02

Band 4_15 MHz_High_QPSK_RB75#0




Date: 24.DEC.2021 17:46:33

Band 4_15 MHz_High_16QAM_RB75#0




Date: 24.DEC.2021 17:46:56

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 24.DEC.2021 17:47:34

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 24.DEC.2021 17:47:58

Band 4_20 MHz_High_QPSK_RB100#0




Date: 24.DEC.2021 17:48:28

Band 4_20 MHz_High_16QAM_RB100#0




Date: 24.DEC.2021 17:48:58

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 10.JAN.2022 20:58:50

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 10.JAN.2022 20:59:34

Band 7_5 MHz_High_QPSK_RB25#0




Date: 24.DEC.2021 17:49:51

Band 7_5 MHz_High_16QAM_RB25#0




Date: 24.DEC.2021 17:50:08

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 24.DEC.2021 17:50:32

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 24.DEC.2021 17:50:59

Band 7_10 MHz_High_QPSK_RB50#0




Date: 24.DEC.2021 17:51:21

Band 7_10 MHz_High_16QAM_RB50#0




Date: 24.DEC.2021 17:51:52

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 24.DEC.2021 17:52:24

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 24.DEC.2021 17:52:50

Band 7_15 MHz_High_QPSK_RB75#0




Date: 24.DEC.2021 17:53:14

Band 7_15 MHz_High_16QAM_RB75#0




Date: 24.DEC.2021 17:53:44

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 24.DEC.2021 17:54:19

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 24.DEC.2021 17:54:52

Band 7_20 MHz_High_QPSK_RB100#0




Date: 24.DEC.2021 17:55:16

Band 7_20 MHz_High_16QAM_RB100#0




Date: 24.DEC.2021 17:55:43

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 10.JAN.2022 21:01:55

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 10.JAN.2022 21:04:07

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 10.JAN.2022 21:05:00

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 10.JAN.2022 21:05:29

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 10.JAN.2022 21:06:33

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 10.JAN.2022 21:06:58

Band 12_3 MHz_High_QPSK_RB15#0




Date: 10.JAN.2022 21:07:37

Band 12_3 MHz_High_16QAM_RB15#0




Date: 10.JAN.2022 21:07:53

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 10.JAN.2022 21:09:25

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 10.JAN.2022 21:09:56

Band 12_5 MHz_High_QPSK_RB25#0




Date: 10.JAN.2022 21:11:01

Band 12_5 MHz_High_16QAM_RB25#0




Date: 10.JAN.2022 21:13:07

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 10.JAN.2022 21:16:35

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 10.JAN.2022 21:17:03

Band 12_10 MHz_High_QPSK_RB50#0




Date: 10.JAN.2022 21:17:41

Band 12_10 MHz_High_16QAM_RB50#0




Date: 10.JAN.2022 21:18:10

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 10.JAN.2022 21:30:28

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 10.JAN.2022 21:31:07

Band 17_5 MHz_High_QPSK_RB25#0




Date: 10.JAN.2022 21:31:40

Band 17_5 MHz_High_16QAM_RB25#0




Date: 10.JAN.2022 21:32:04

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 24.DEC.2021 18:02:01

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 24.DEC.2021 18:02:29

Band 17_10 MHz_High_QPSK_RB50#0



Date: 24.DEC.2021 18:02:57

Band 17_10 MHz_High_16QAM_RB50#0



Date: 24.DEC.2021 18:03:25