



RF Declaration Letter

2019-04-03

To:

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Product Name : Elevator IOT Machine

Model Name : SOTL5-b

Series Model Name : xSOTL5x (x - Where x may be any combination of alphanumeric characters or "-" or blank.)

FCC ID : 2AR8LSOTL5B

We hereby declare that firmware was set in SOTL5-b had disable Wi-Fi 802.11 n HT40 (2.4G) and 802.11 an+ac (5GHz) support upon system boot-up for all SOTL5-b and xSOTL5x (x - Where x may be any combination of alphanumeric characters or "-" or blank.) system shipment. Consequently, users are NOT accessible to Wi-Fi 802.11 n HT40 (2.4G) and 802.11 an+ac (5GHz).

Datahoist, Inc. assumes the liability against any problems or damages that might occur in relation to this issue.

Sincerely Yours,

Dan Bryant/CEO

dbryant@datahoist.com

8920 Business Park Drive #250, AUSTIN, TX 78759 USA