



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 16.SEP.2022 16:47:12

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 16.SEP.2022 16:47:31

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 16.SEP.2022 16:47:50

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 16.SEP.2022 16:48:05

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 16.SEP.2022 16:48:30

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 16.SEP.2022 16:48:51

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 16.SEP.2022 16:49:34

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 16.SEP.2022 16:49:52

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 16.SEP.2022 16:50:15

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 16.SEP.2022 16:50:34

Band 2_3 MHz_High_QPSK_RB15#0




Date: 16.SEP.2022 16:50:52

Band 2_3 MHz_High_16QAM_RB15#0




Date: 16.SEP.2022 16:51:10

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 16.SEP.2022 16:52:08

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 16.SEP.2022 16:52:30

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 16.SEP.2022 16:52:49

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 16.SEP.2022 16:53:11

Band 2_5 MHz_High_QPSK_RB25#0




Date: 16.SEP.2022 16:53:30

Band 2_5 MHz_High_16QAM_RB25#0




Date: 16.SEP.2022 16:53:55

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 16.SEP.2022 16:54:46

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 16.SEP.2022 16:55:15

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 16.SEP.2022 16:55:38

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 16.SEP.2022 16:56:04

Band 2_10 MHz_High_QPSK_RB50#0




Date: 16.SEP.2022 16:56:26

Band 2_10 MHz_High_16QAM_RB50#0




Date: 16.SEP.2022 16:56:49


Band 2_15 MHz_Low_QPSK_RB75#0



Band 2_15 MHz_Low_16QAM_RB75#0




Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 16.SEP.2022 16:58:34

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 16.SEP.2022 16:59:02

Band 2_15 MHz_High_QPSK_RB75#0




Date: 16.SEP.2022 16:59:31

Band 2_15 MHz_High_16QAM_RB75#0




Date: 16.SEP.2022 17:00:03

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 16.SEP.2022 17:00:58

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 16.SEP.2022 17:01:29

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 16.SEP.2022 17:02:02

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 16.SEP.2022 17:02:28

Band 2_20 MHz_High_QPSK_RB100#0




Date: 16.SEP.2022 17:03:01

Band 2_20 MHz_High_16QAM_RB100#0




Date: 16.SEP.2022 17:03:32

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 16.SEP.2022 17:03:50

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 16.SEP.2022 17:04:08


Band 4_1.4 MHz_Middle_QPSK_RB6#0



Band 4_1.4 MHz_Middle_16QAM_RB6#0




Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 16.SEP.2022 17:04:57

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 16.SEP.2022 17:05:15

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 16.SEP.2022 17:06:06

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 16.SEP.2022 17:06:24

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 16.SEP.2022 17:06:46

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 16.SEP.2022 17:07:05

Band 4_3 MHz_High_QPSK_RB15#0




Date: 16.SEP.2022 17:07:24

Band 4_3 MHz_High_16QAM_RB15#0




Date: 16.SEP.2022 17:07:42

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 16.SEP.2022 17:08:30

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 16.SEP.2022 17:08:48

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 16.SEP.2022 17:09:07

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 16.SEP.2022 17:09:26

Band 4_5 MHz_High_QPSK_RB25#0




Date: 16.SEP.2022 17:09:45

Band 4_5 MHz_High_16QAM_RB25#0




Date: 16.SEP.2022 17:10:07

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 16.SEP.2022 17:11:06

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 16.SEP.2022 17:11:28

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 16.SEP.2022 17:11:55

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 16.SEP.2022 17:12:27

Band 4_10 MHz_High_QPSK_RB50#0




Date: 16.SEP.2022 17:12:53

Band 4_10 MHz_High_16QAM_RB50#0




Date: 16.SEP.2022 17:13:13

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 16.SEP.2022 17:14:13

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 16.SEP.2022 17:14:47

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 16.SEP.2022 17:15:13

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 16.SEP.2022 17:15:42

Band 4_15 MHz_High_QPSK_RB75#0




Date: 16.SEP.2022 17:16:07

Band 4_15 MHz_High_16QAM_RB75#0




Date: 16.SEP.2022 17:16:39

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 16.SEP.2022 17:34:59

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 16.SEP.2022 17:35:24

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 16.SEP.2022 17:36:04

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 16.SEP.2022 17:36:43

Band 4_20 MHz_High_QPSK_RB100#0




Date: 16.SEP.2022 17:37:13

Band 4_20 MHz_High_16QAM_RB100#0




Date: 16.SEP.2022 17:37:39

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 16.SEP.2022 17:37:57

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 16.SEP.2022 17:38:16

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 16.SEP.2022 17:38:38

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 16.SEP.2022 17:38:56

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 16.SEP.2022 17:39:15

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 16.SEP.2022 17:39:37

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 16.SEP.2022 17:42:05

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 16.SEP.2022 17:42:20

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 16.SEP.2022 17:42:39

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 16.SEP.2022 17:42:58

Band 5_3 MHz_High_QPSK_RB15#0




Date: 16.SEP.2022 17:43:17

Band 5_3 MHz_High_16QAM_RB15#0




Date: 16.SEP.2022 17:43:35

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 16.SEP.2022 17:44:34

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 16.SEP.2022 17:44:53

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 16.SEP.2022 17:45:15

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 16.SEP.2022 17:45:34

Band 5_5 MHz_High_QPSK_RB25#0




Date: 16.SEP.2022 17:46:00

Band 5_5 MHz_High_16QAM_RB25#0




Date: 16.SEP.2022 17:46:25

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 16.SEP.2022 17:47:39

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 16.SEP.2022 17:47:59

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 16.SEP.2022 17:48:25

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 16.SEP.2022 17:48:48

Band 5_10 MHz_High_QPSK_RB50#0



Date: 16.SEP.2022 17:49:19


Band 5_10 MHz_High_16QAM_RB50#0




Date: 16.SEP.2022 17:49:44

Please refer to following plots:


and 7_5 MHz_Low_QPSK_RB25#0



Band 7_5 MHz_Low_16QAM_RB25#0




Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 17.SEP.2022 10:02:48

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 17.SEP.2022 10:03:12

Band 7_5 MHz_High_QPSK_RB25#0




Date: 17.SEP.2022 10:03:37

Band 7_5 MHz_High_16QAM_RB25#0




Date: 17.SEP.2022 10:03:58

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 17.SEP.2022 10:05:02

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 17.SEP.2022 10:05:26

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 17.SEP.2022 10:05:51

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 17.SEP.2022 10:06:16

Band 7_10 MHz_High_QPSK_RB50#0




Date: 17.SEP.2022 10:06:41

Band 7_10 MHz_High_16QAM_RB50#0




Date: 17.SEP.2022 10:07:02

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 17.SEP.2022 10:27:16

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 17.SEP.2022 10:27:45

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 17.SEP.2022 10:28:12

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 17.SEP.2022 10:28:42

Band 7_15 MHz_High_QPSK_RB75#0




Date: 17.SEP.2022 10:29:05

Band 7_15 MHz_High_16QAM_RB75#0




Date: 17.SEP.2022 10:29:33

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 17.SEP.2022 10:41:43

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 17.SEP.2022 10:42:13

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 17.SEP.2022 10:42:39

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 17.SEP.2022 10:43:12

Band 7_20 MHz_High_QPSK_RB100#0




Date: 17.SEP.2022 10:43:49

Band 7_20 MHz_High_16QAM_RB100#0




Date: 17.SEP.2022 10:44:19

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 17.SEP.2022 10:54:39

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 17.SEP.2022 10:54:57

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 17.SEP.2022 10:55:21

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 17.SEP.2022 10:55:39

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 17.SEP.2022 10:55:54

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 17.SEP.2022 10:56:15

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 17.SEP.2022 10:57:19

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 17.SEP.2022 10:57:37

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 17.SEP.2022 10:57:55

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 17.SEP.2022 10:58:09

Band 12_3 MHz_High_QPSK_RB15#0




Date: 17.SEP.2022 10:58:27

Band 12_3 MHz_High_16QAM_RB15#0




Date: 17.SEP.2022 10:58:44

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 17.SEP.2022 10:59:45

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 17.SEP.2022 11:00:03

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 17.SEP.2022 11:00:22

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 17.SEP.2022 11:00:39

Band 12_5 MHz_High_QPSK_RB25#0




Date: 17.SEP.2022 11:01:01

Band 12_5 MHz_High_16QAM_RB25#0




Date: 17.SEP.2022 11:01:16

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 17.SEP.2022 11:02:21

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 17.SEP.2022 11:02:42

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 17.SEP.2022 11:03:10

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 17.SEP.2022 11:03:37

Band 12_10 MHz_High_QPSK_RB50#0




Date: 17.SEP.2022 11:04:05

Band 12_10 MHz_High_16QAM_RB50#0




Date: 17.SEP.2022 11:04:23

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 17.SEP.2022 11:04:44

Band 66_1.4 MHz_Low_16QAM_RB6#0



Date: 17.SEP.2022 11:05:02

Band 66_1.4 MHz_Middle_QPSK_RB6#0




Date: 17.SEP.2022 11:05:16

Band 66_1.4 MHz_Middle_16QAM_RB6#0




Date: 17.SEP.2022 11:05:31

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 17.SEP.2022 11:05:49

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 17.SEP.2022 11:06:06

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 17.SEP.2022 11:06:46

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 17.SEP.2022 11:07:04

Band 66_3 MHz_Middle_QPSK_RB15#0




Date: 17.SEP.2022 11:07:22

Band 66_3 MHz_Middle_16QAM_RB15#0




Date: 17.SEP.2022 11:07:39

Band 66_3 MHz_High_QPSK_RB15#0




Date: 17.SEP.2022 11:07:54

Band 66_3 MHz_High_16QAM_RB15#0




Date: 17.SEP.2022 11:08:14

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 17.SEP.2022 11:08:56

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 17.SEP.2022 11:09:14

Band 66_5 MHz_Middle_QPSK_RB25#0




Date: 17.SEP.2022 11:09:36

Band 66_5 MHz_Middle_16QAM_RB25#0




Date: 17.SEP.2022 11:09:53

Band 66_5 MHz_High_QPSK_RB25#0




Date: 17.SEP.2022 11:10:15

Band 66_5 MHz_High_16QAM_RB25#0




Date: 17.SEP.2022 11:10:36

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 17.SEP.2022 11:11:32

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 17.SEP.2022 11:11:56

Band 66_10 MHz_Middle_QPSK_RB50#0




Date: 17.SEP.2022 11:12:24

Band 66_10 MHz_Middle_16QAM_RB50#0




Date: 17.SEP.2022 11:12:54

Band 66_10 MHz_High_QPSK_RB50#0




Date: 17.SEP.2022 11:13:19

Band 66_10 MHz_High_16QAM_RB50#0



Date: 17.SEP.2022 11:13:44

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 17.SEP.2022 11:14:43

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 17.SEP.2022 11:15:12

Band 66_15 MHz_Middle_QPSK_RB75#0




Date: 17.SEP.2022 11:15:39

Band 66_15 MHz_Middle_16QAM_RB75#0




Date: 17.SEP.2022 11:16:05

Band 66_15 MHz_High_QPSK_RB75#0




Date: 17.SEP.2022 11:16:32

Band 66_15 MHz_High_16QAM_RB75#0




Date: 17.SEP.2022 11:17:01

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 17.SEP.2022 11:18:00

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 17.SEP.2022 11:18:27

Band 66_20 MHz_Middle_QPSK_RB100#0




Date: 17.SEP.2022 11:18:57

Band 66_20 MHz_Middle_16QAM_RB100#0




Date: 17.SEP.2022 11:19:27

Band 66_20 MHz_High_QPSK_RB100#0



Date: 17.SEP.2022 11:20:00


Band 66_20 MHz_High_16QAM_RB100#0




Date: 17.SEP.2022 11:20:29

Please refer to following plots:


and 17_5 MHz_Low_QPSK_RB25#0



Band 17_5 MHz_Low_16QAM_RB25#0




Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 17.SEP.2022 17:53:18

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 17.SEP.2022 17:53:40

Band 17_5 MHz_High_QPSK_RB25#0




Date: 17.SEP.2022 17:54:02

Band 17_5 MHz_High_16QAM_RB25#0




Date: 17.SEP.2022 17:54:24

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 17.SEP.2022 17:55:33

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 17.SEP.2022 17:55:59

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 17.SEP.2022 17:56:26

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 17.SEP.2022 17:56:51

Band 17_10 MHz_High_QPSK_RB50#0



Date: 17.SEP.2022 17:57:15

Band 17_10 MHz_High_16QAM_RB50#0



Date: 17.SEP.2022 17:57:34