



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:17:33

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:18:03

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:18:29

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:18:59

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:19:31

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:20:01

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:21:01

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:21:30

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)





Date: 16.SEP.2022 18:22:03


Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)



Date: 16.SEP.2022 18:22:26




Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:24:30

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:24:53

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:25:23

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:25:46

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:26:21

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:26:45

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:27:45

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:28:08

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:28:38

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:29:01

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:29:24

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:29:50

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:31:13

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:31:44

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:32:13

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:32:44

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:33:14

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:33:40

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:34:48

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:35:21

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:35:54

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:36:17

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:36:50

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:37:20

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:37:52

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:38:12

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:38:47

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:39:17

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)





Date: 16.SEP.2022 18:39:52


Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)



Date: 16.SEP.2022 18:40:16




Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:42:09

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:42:39

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:43:15

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:43:35

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:44:39

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:45:09

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)





Date: 16.SEP.2022 18:45:39


Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)



Date: 16.SEP.2022 18:46:02




Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:47:52

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:48:12

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:48:42

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:49:02

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:49:32

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:49:56

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:50:50

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:51:13

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:51:46

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:52:13

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:52:43

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:53:13

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:54:04

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:54:28

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:54:55

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:55:22

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:55:52

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.SEP.2022 18:56:12

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:57:11

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.SEP.2022 18:57:41

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:58:11

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.SEP.2022 18:58:41

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.SEP.2022 18:59:10

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.SEP.2022 18:59:30

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:00:27

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:00:58

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:01:30

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:01:51

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:02:17

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:02:54

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:03:47

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:04:20

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)





Date: 16.SEP.2022 19:04:53


Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)



Date: 16.SEP.2022 19:05:20




Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:07:16

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:07:43

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:08:20

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:08:50

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.SEP.2022 19:09:26

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.SEP.2022 19:09:46

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:40:35

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:41:12

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)





Date: 17.SEP.2022 11:41:54


Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)



Date: 17.SEP.2022 11:42:20




Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:44:17

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:44:47

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:45:19

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:45:39

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:46:11

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:46:45

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:47:47

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:48:10

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:48:43

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:49:06

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:49:35

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:49:59

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:51:01

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:51:31

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:52:04

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:52:30

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 11:53:03

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:53:29

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:06:52

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:07:15

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:07:41

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:08:04

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17-SEP-2022 12:08:37

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17-SEP-2022 12:09:00

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:10:00

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:10:30

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:11:01

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:11:25

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:11:47

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:12:17

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:13:08

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:13:37

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:14:00

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:14:29

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:14:59

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:15:25

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:16:13

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:16:42

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:17:11

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:17:41

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:18:11

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.SEP.2022 12:18:37

Band 66_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:19:12

Band 66_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:19:35

Band 66_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:20:03

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:20:23

Band 66_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:20:59

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:21:25

Band 66_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:22:22

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:22:45

Band 66_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:23:17

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:23:44

Band 66_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:24:13

Band 66_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:24:43

Band 66_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:26:02

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:26:26

Band 66_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:27:02

Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:27:28

Band 66_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:28:01

Band 66_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:28:27

Band 66_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:29:21

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:29:54

Band 66_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:30:23

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:30:50

Band 66_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:31:25

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:31:46

Band 66_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:32:43

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:33:09

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:33:42

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:34:05

Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:34:35

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:35:01

Band 66_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:36:52

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:37:15

Band 66_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:37:45

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:38:15

Band 66_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.SEP.2022 12:38:42

Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.SEP.2022 12:39:05

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 18:44:30

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 18:44:50

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 18:45:23

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 18:45:48

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.SEP.2022 18:46:17

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.SEP.2022 18:46:45

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 18:47:44

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.SEP.2022 18:48:12

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.SEP.2022 18:48:43

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.SEP.2022 18:49:16

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 17.SEP.2022 18:49:50

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)



Date: 17.SEP.2022 18:50:10