


FCC Part 27 & IC RSS-195


LTE Band 30, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~2270MHz)




5MHz_Low_QPSK_1@0(2370MHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~26GHz)




5MHz_Middle_QPSK_1@0(30MHz~2270MHz)




5MHz_Middle_QPSK_1@0(2370MHz~15GHz)



5MHz_Middle_QPSK_1@0(15GHz~26GHz)




5MHz_High_QPSK_1@0(30MHz~2270MHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:36:50

5MHz_High_QPSK_1@0(2370MHz~15GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:37:05

5MHz_High_QPSK_1@0(15GHz~26GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:37:20

10MHz_Middle_QPSK_1@0(30MHz~2270MHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:38:02

10MHz_Middle_QPSK_1@0(2370MHz~15GHz)



ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:38:18

10MHz_Middle_QPSK_1@0(15GHz~26GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 13:38:34

FCC Part 27 & IC RSS-139


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:09:50

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:10:11

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:10:30

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:11:24

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:11:44

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:12:04

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:12:55

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:13:15

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:13:35

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:14:27

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:14:47

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 11.JAN.2026 15:15:07

FCC Part 27 & IC RSS-130


LTE Band 71, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:41:22

5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:41:48

5MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:42:23

10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:45:10

10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:45:35

10MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Pu
Date: 12.JAN.2026 09:47:10

15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:47:58

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:54:10

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:49:08

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:50:04

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:50:31

20MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2602P27730E-RF Tester:Permin Fu
Date: 12.JAN.2026 09:51:21

FCC Part 90 & IC RSS-140


LTE Band 14, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.98GHz)




5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




5MHz_Middle_QPSK_1@0(30MHz~8.98GHz)




5MHz_Middle_QPSK_1@0(1559MHz~1610MHz)





5MHz_High_QPSK_1@0(30MHz~8.98GHz)



5MHz_High_QPSK_1@0(1559MHz~1610MHz)





***** END *****