



10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:20:01

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:20:24

10MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:20:46

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:21:12

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:21:34

10MHz_High_QPSK_1@0(15GHz~25.65GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:21:57

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:22:25

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:22:48

15MHz_Low_QPSK_1@0(15GHz~25.075GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:23:10

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:23:36

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:24:00

15MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:24:22

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:24:47

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:25:10

15MHz_High_QPSK_1@0(15GHz~25.625GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:25:34

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:26:01

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:26:24

20MHz_Low_QPSK_1@0(15GHz~25.1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:26:46

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:27:11

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:27:35

20MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:27:58

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:28:22

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:28:46

20MHz_High_QPSK_1@0(15GHz~25.6GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 00:29:09

FCC Part 27 & IC RSS-130

LTE Band 12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:04:11

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:04:41

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:05:12

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:05:45

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:06:15

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:06:47

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:07:21

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:07:51

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:08:21

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:08:53

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:09:23

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:09:52

FCC Part 27 & IC RSS-130

LTE Band 17, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:11:16

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:11:47

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:12:16

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:12:49

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:13:19

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:13:50

FCC Part 27 & IC RSS-139

LTE Band 66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:17:02

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:17:33

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:18:06

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:18:42

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:19:13

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:19:44

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:20:19

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:20:50

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:21:21

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:21:54

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:22:27

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:22:57

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:23:31

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:24:03

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:24:35

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:25:10

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:25:43

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 9.MAR.2026 21:26:14

FCC Part 27 & IC RSS-130


LTE Band 71, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:20:02

5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:23:03

5MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:23:33

10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 09:50:14

10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:25:00

10MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 09:54:06

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:29:13

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:36:28

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2502A31388E-RF Tester:Levi Shi
Date: 26.FEB.2026 10:39:34

Page231 of 231