





11AC20MIMO-Ant0-5200-PASS




11AC20MIMO-Ant1-5200-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20MIMO-Ant0-5240-PASS




11AC20MIMO-Ant1-5240-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40MIMO-Ant0-5230-PASS




11AC40MIMO-Ant1-5230-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant0-5200-PASS




11AX20MIMO-Ant1-5200-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40MIMO-Ant0-5190-PASS




11AX40MIMO-Ant1-5190-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Test Graphs B4




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant0-5785-PASS





11A-Ant1-5785-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com





11N20MIMO-Ant0-5745-PASS




11N20MIMO-Ant1-5745-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11N20MIMO-Ant0-5785-PASS




11N20MIMO-Ant1-5785-PASS




11N20MIMO-Ant0-5825-PASS




11N20MIMO-Ant1-5825-PASS



11N40MIMO-Ant0-5755-PASS




11N40MIMO-Ant1-5755-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20MIMO-Ant0-5745-PASS




11AC20MIMO-Ant1-5745-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11AC20MIMO-Ant0-5825-PASS




11AC20MIMO-Ant1-5825-PASS




11AC40MIMO-Ant0-5755-PASS



11AC40MIMO-Ant1-5755-PASS



11AC40MIMO-Ant0-5795-PASS




11AC40MIMO-Ant1-5795-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant0-5745-PASS




11AX20MIMO-Ant1-5745-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant0-5825-PASS




11AX20MIMO-Ant1-5825-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: Band edge measurements

Test Result B1

Test Mode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant0	Low	5180	-36.36	≤-27	PASS
11A	Ant1	Low	5180	-35.03	≤-27	PASS
11A	Ant0	High	5240	-43.96	≤-27	PASS
11A	Ant1	High	5240	-43.02	≤-27	PASS
11N20MIMO	Ant0	Low	5180	-35.62	≤-27	PASS
11N20MIMO	Ant1	Low	5180	-34.81	≤-27	PASS
11N20MIMO	Ant0	High	5240	-43.56	≤-27	PASS
11N20MIMO	Ant1	High	5240	-43.08	≤-27	PASS
11N40MIMO	Ant0	Low	5190	-35.49	≤-27	PASS
11N40MIMO	Ant1	Low	5190	-35.09	≤-27	PASS
11N40MIMO	Ant0	High	5230	-43.69	≤-27	PASS
11N40MIMO	Ant1	High	5230	-43.67	≤-27	PASS
11AC20MIMO	Ant0	Low	5180	-36.08	≤-27	PASS
11AC20MIMO	Ant1	Low	5180	-35.39	≤-27	PASS
11AC20MIMO	Ant0	High	5240	-44.6	≤-27	PASS
11AC20MIMO	Ant1	High	5240	-42.65	≤-27	PASS
11AC40MIMO	Ant0	Low	5190	-36.15	≤-27	PASS
11AC40MIMO	Ant1	Low	5190	-35.37	≤-27	PASS
11AC40MIMO	Ant0	High	5230	-43.84	≤-27	PASS
11AC40MIMO	Ant1	High	5230	-44.09	≤-27	PASS
11AX20MIMO	Ant0	Low	5180	-35.19	≤-27	PASS
11AX20MIMO	Ant1	Low	5180	-35.5	≤-27	PASS
11AX20MIMO	Ant0	High	5240	-43.85	≤-27	PASS
11AX20MIMO	Ant1	High	5240	-42.88	≤-27	PASS
11AX40MIMO	Ant0	Low	5190	-35.77	≤-27	PASS
11AX40MIMO	Ant1	Low	5190	-35.72	≤-27	PASS
11AX40MIMO	Ant0	High	5230	-43.79	≤-27	PASS
11AX40MIMO	Ant1	High	5230	-43.24	≤-27	PASS

Note: The margin plus the antenna gain also meets the limit.

Test Result B4

Test Mode	Antenna	Ch. Name	Frequency [MHz]	FreqRange [MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant0	Low	5745	5720~5725	-43.03	≤15.98	PASS
11A	Ant0	Low	5745	5700~5720	-43.51	≤10.89	PASS
11A	Ant0	Low	5745	5650~5700	-46.25	≤-26.26	PASS
11A	Ant0	Low	5745	5760~5650	-46.46	≤-27	PASS
11A	Ant1	Low	5745	5720~5725	-40.31	≤17.12	PASS
11A	Ant1	Low	5745	5700~5720	-44.86	≤10.47	PASS
11A	Ant1	Low	5745	5650~5700	-47.53	≤-26.88	PASS
11A	Ant1	Low	5745	5760~5650	-46.56	≤-27	PASS
11A	Ant0	High	5825	5850~5855	-42.75	≤16.54	PASS
11A	Ant0	High	5825	5855~5875	-44.26	≤10.95	PASS
11A	Ant0	High	5825	5875~5925	-46.63	≤-26.87	PASS
11A	Ant0	High	5825	5925~5935	-45.41	≤-27	PASS
11A	Ant1	High	5825	5850~5855	-44.98	≤15.65	PASS
11A	Ant1	High	5825	5855~5875	-44.85	≤10.24	PASS
11A	Ant1	High	5825	5875~5925	-46.25	≤-26.87	PASS
11A	Ant1	High	5825	5925~5935	-44.25	≤-27	PASS
11N20MIMO	Ant0	Low	5745	5720~5725	-37.73	≤15.98	PASS
11N20MIMO	Ant0	Low	5745	5700~5720	-36.4	≤15.23	PASS
11N20MIMO	Ant0	Low	5745	5650~5700	-47	≤-26.88	PASS
11N20MIMO	Ant0	Low	5745	5760~5650	-46.87	≤-27	PASS
11N20MIMO	Ant1	Low	5745	5720~5725	-37.56	≤15.98	PASS
11N20MIMO	Ant1	Low	5745	5700~5720	-40.86	≤11.12	PASS
11N20MIMO	Ant1	Low	5745	5650~5700	-47.15	≤-26.26	PASS
11N20MIMO	Ant1	Low	5745	5760~5650	-44.89	≤-27	PASS
11N20MIMO	Ant0	High	5825	5850~5855	-43.05	≤15.65	PASS
11N20MIMO	Ant0	High	5825	5855~5875	-45.06	≤10.51	PASS
11N20MIMO	Ant0	High	5825	5875~5925	-45.38	≤-26.00	PASS
11N20MIMO	Ant0	High	5825	5925~5935	-45.3	≤-27	PASS
11N20MIMO	Ant1	High	5825	5850~5855	-44.06	≤15.65	PASS
11N20MIMO	Ant1	High	5825	5855~5875	-44.12	≤10.24	PASS
11N20MIMO	Ant1	High	5825	5875~5925	-44.25	≤-26.87	PASS
11N20MIMO	Ant1	High	5825	5925~5935	-44.76	≤-27	PASS
11N40MIMO	Ant0	Low	5755	5720~5725	-35.4	≤16.34	PASS
11N40MIMO	Ant0	Low	5755	5700~5720	-36.31	≤14.76	PASS
11N40MIMO	Ant0	Low	5755	5650~5700	-46.97	≤-26.94	PASS
11N40MIMO	Ant0	Low	5755	5780~5650	-44.5	≤-27	PASS
11N40MIMO	Ant1	Low	5755	5720~5725	-36.33	≤15.90	PASS
11N40MIMO	Ant1	Low	5755	5700~5720	-36.13	≤14.87	PASS
11N40MIMO	Ant1	Low	5755	5650~5700	-45.47	≤-26.50	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11N40MIMO	Ant1	Low	5755	5780~5650	-45.88	≤-27	PASS
11N40MIMO	Ant0	High	5795	5850~5855	-44.18	≤15.85	PASS
11N40MIMO	Ant0	High	5795	5855~5875	-43.4	≤11.61	PASS
11N40MIMO	Ant0	High	5795	5875~5925	-45.67	≤-26.26	PASS
11N40MIMO	Ant0	High	5795	5925~5935	-45.35	≤-27	PASS
11N40MIMO	Ant1	High	5795	5850~5855	-45.45	≤15.85	PASS
11N40MIMO	Ant1	High	5795	5855~5875	-43.63	≤11.28	PASS
11N40MIMO	Ant1	High	5795	5875~5925	-46.82	≤-26.97	PASS
11N40MIMO	Ant1	High	5795	5925~5935	-45.18	≤-27	PASS
11AC20MIMO	Ant0	Low	5745	5720~5725	-38.13	≤17.12	PASS
11AC20MIMO	Ant0	Low	5745	5700~5720	-43.86	≤10.51	PASS
11AC20MIMO	Ant0	Low	5745	5650~5700	-46.44	≤-26.88	PASS
11AC20MIMO	Ant0	Low	5745	5760~5650	-45.51	≤-27	PASS
11AC20MIMO	Ant1	Low	5745	5720~5725	-42.93	≤15.98	PASS
11AC20MIMO	Ant1	Low	5745	5700~5720	-43.58	≤10.47	PASS
11AC20MIMO	Ant1	Low	5745	5650~5700	-44.77	≤-25.03	PASS
11AC20MIMO	Ant1	Low	5745	5760~5650	-45.72	≤-27	PASS
11AC20MIMO	Ant0	High	5825	5850~5855	-44.04	≤16.10	PASS
11AC20MIMO	Ant0	High	5825	5855~5875	-43.22	≤11.39	PASS
11AC20MIMO	Ant0	High	5825	5875~5925	-44.72	≤-26.29	PASS
11AC20MIMO	Ant0	High	5825	5925~5935	-45.6	≤-27	PASS
11AC20MIMO	Ant1	High	5825	5850~5855	-44.78	≤15.65	PASS
11AC20MIMO	Ant1	High	5825	5855~5875	-43.2	≤12.37	PASS
11AC20MIMO	Ant1	High	5825	5875~5925	-46.99	≤-26.87	PASS
11AC20MIMO	Ant1	High	5825	5925~5935	-45.63	≤-27	PASS
11AC40MIMO	Ant0	Low	5755	5720~5725	-36.87	≤15.90	PASS
11AC40MIMO	Ant0	Low	5755	5700~5720	-36.6	≤14.49	PASS
11AC40MIMO	Ant0	Low	5755	5650~5700	-45.13	≤-25.63	PASS
11AC40MIMO	Ant0	Low	5755	5780~5650	-45.56	≤-27	PASS
11AC40MIMO	Ant1	Low	5755	5720~5725	-38.83	≤15.90	PASS
11AC40MIMO	Ant1	Low	5755	5700~5720	-39.94	≤12.29	PASS
11AC40MIMO	Ant1	Low	5755	5650~5700	-45.59	≤-26.94	PASS
11AC40MIMO	Ant1	Low	5755	5780~5650	-45.32	≤-27	PASS
11AC40MIMO	Ant0	High	5795	5850~5855	-45.19	≤15.85	PASS
11AC40MIMO	Ant0	High	5795	5855~5875	-43.31	≤11.55	PASS
11AC40MIMO	Ant0	High	5795	5875~5925	-46.63	≤-26.44	PASS
11AC40MIMO	Ant0	High	5795	5925~5935	-45.46	≤-27	PASS
11AC40MIMO	Ant1	High	5795	5850~5855	-44.75	≤15.85	PASS
11AC40MIMO	Ant1	High	5795	5855~5875	-44.19	≤10.14	PASS
11AC40MIMO	Ant1	High	5795	5875~5925	-45.99	≤-26.61	PASS
11AC40MIMO	Ant1	High	5795	5925~5935	-45.54	≤-27	PASS
11AX20MIMO	Ant0	Low	5745	5720~5725	-43.02	≤15.98	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX20MIMO	Ant0	Low	5745	5700~5720	-43.71	≤10.23	PASS
11AX20MIMO	Ant0	Low	5745	5650~5700	-45.98	≤-26.26	PASS
11AX20MIMO	Ant0	Low	5745	5760~5650	-46.5	≤-27	PASS
11AX20MIMO	Ant1	Low	5745	5720~5725	-42.1	≤15.98	PASS
11AX20MIMO	Ant1	Low	5745	5700~5720	-43.17	≤11.63	PASS
11AX20MIMO	Ant1	Low	5745	5650~5700	-47.01	≤-26.88	PASS
11AX20MIMO	Ant1	Low	5745	5760~5650	-45.43	≤-27	PASS
11AX20MIMO	Ant0	High	5825	5850~5855	-39.48	≤15.65	PASS
11AX20MIMO	Ant0	High	5825	5855~5875	-39.21	≤15.44	PASS
11AX20MIMO	Ant0	High	5825	5875~5925	-45.74	≤-26.87	PASS
11AX20MIMO	Ant0	High	5825	5925~5935	-45.56	≤-27	PASS
11AX20MIMO	Ant1	High	5825	5850~5855	-43.61	≤15.65	PASS
11AX20MIMO	Ant1	High	5825	5855~5875	-44	≤10.24	PASS
11AX20MIMO	Ant1	High	5825	5875~5925	-46.32	≤-26.87	PASS
11AX20MIMO	Ant1	High	5825	5925~5935	-45.54	≤-27	PASS
11AX40MIMO	Ant0	Low	5755	5720~5725	-37	≤15.90	PASS
11AX40MIMO	Ant0	Low	5755	5700~5720	-36.22	≤15.47	PASS
11AX40MIMO	Ant0	Low	5755	5650~5700	-46.43	≤-26.94	PASS
11AX40MIMO	Ant0	Low	5755	5780~5650	-44.25	≤-27	PASS
11AX40MIMO	Ant1	Low	5755	5720~5725	-32.74	≤17.24	PASS
11AX40MIMO	Ant1	Low	5755	5700~5720	-35.59	≤15.58	PASS
11AX40MIMO	Ant1	Low	5755	5650~5700	-47.34	≤-26.94	PASS
11AX40MIMO	Ant1	Low	5755	5780~5650	-46.01	≤-27	PASS
11AX40MIMO	Ant0	High	5795	5850~5855	-46.12	≤15.85	PASS
11AX40MIMO	Ant0	High	5795	5855~5875	-44.83	≤10.47	PASS
11AX40MIMO	Ant0	High	5795	5875~5925	-47.62	≤-26.97	PASS
11AX40MIMO	Ant0	High	5795	5925~5935	-45.11	≤-27	PASS
11AX40MIMO	Ant1	High	5795	5850~5855	-44.87	≤15.85	PASS
11AX40MIMO	Ant1	High	5795	5855~5875	-44.27	≤10.74	PASS
11AX40MIMO	Ant1	High	5795	5875~5925	-45.38	≤-26.97	PASS
11AX40MIMO	Ant1	High	5795	5925~5935	-44.79	≤-27	PASS


Note: The margin plus the antenna gain also meets the limit.

Test Graphs B1








11A-Ant0-5240-PASS




11A-Ant1-5240-PASS












11N40MIMO-Ant0-5230-PASS




11N40MIMO-Ant1-5230-PASS













11AC40MIMO-Ant0-5230-PASS




11AC40MIMO-Ant1-5230-PASS












Test Graphs B4








11A-Ant0-5825-PASS




11A-Ant1-5825-PASS









11N40MIMO-Ant0-5755-PASS




11N40MIMO-Ant1-5755-PASS



11N40MIMO-Ant0-5795-PASS




11N40MIMO-Ant1-5795-PASS



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





---End---