


Appendix C


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 21.APR.2022 18:14:48

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 21.APR.2022 18:15:01

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 21.APR.2022 18:15:15

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 21.APR.2022 18:15:35

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 21.APR.2022 18:15:53

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 21.APR.2022 18:16:09

Band 2_3 MHz_High_QPSK_RB15#0




Date: 21.APR.2022 18:16:26

Band 2_3 MHz_High_16QAM_RB15#0




Date: 21.APR.2022 18:16:43

Band 2_5 MHz_Low_QPSK_RB25#0



Date: 21.APR.2022 18:17:13

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 21.APR.2022 18:17:33

Band 2_5 MHz_High_QPSK_RB25#0




Date: 21.APR.2022 18:17:56

Band 2_5 MHz_High_16QAM_RB25#0




Date: 21.APR.2022 18:18:18

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 21.APR.2022 18:18:39

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 21.APR.2022 18:19:10

Band 2_10 MHz_High_QPSK_RB50#0




Date: 21.APR.2022 18:19:38

Band 2_10 MHz_High_16QAM_RB50#0




Date: 21.APR.2022 18:20:06

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 21.APR.2022 18:20:40

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 21.APR.2022 18:21:09

Band 2_15 MHz_High_QPSK_RB75#0




Date: 21.APR.2022 18:21:46

Band 2_15 MHz_High_16QAM_RB75#0




Date: 21.APR.2022 18:22:15

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 21.APR.2022 18:22:55

Band 2_20 MHz_Low_16QAM_RB100#0



Date: 21.APR.2022 18:23:37

Band 2_20 MHz_High_QPSK_RB100#0




Date: 21.APR.2022 18:24:16

Band 2_20 MHz_High_16QAM_RB100#0




Date: 21.APR.2022 18:24:42

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 21.APR.2022 18:25:00

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 21.APR.2022 18:25:17

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 22.APR.2022 09:02:32

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 21.APR.2022 18:25:47

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 21.APR.2022 18:26:08

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 21.APR.2022 18:26:28

Band 5_3 MHz_High_QPSK_RB15#0




Date: 21.APR.2022 18:26:45

Band 5_3 MHz_High_16QAM_RB15#0




Date: 21.APR.2022 18:27:01

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 21.APR.2022 18:27:22

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 21.APR.2022 18:27:45

Band 5_5 MHz_High_QPSK_RB25#0




Date: 22.APR.2022 09:03:22

Band 5_5 MHz_High_16QAM_RB25#0




Date: 21.APR.2022 18:28:31

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 21.APR.2022 18:28:58

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 21.APR.2022 18:29:38

Band 5_10 MHz_High_QPSK_RB50#0



Date: 21.APR.2022 18:30:09

Band 5_10 MHz_High_16QAM_RB50#0



Date: 21.APR.2022 18:30:44