



N78-370 0-3800	30	60	DFT-QPSK	M	Outer_Full	NV	40	-13.000000	-0.003467	PASS
N78-370 0-3800	30	60	DFT-QPSK	M	Outer_Full	NV	50	-12.060000	-0.003216	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	-30	-19.360000	-0.005163	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	-20	-14.510000	-0.003869	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	-10	-19.300000	-0.005147	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	0	-10.350000	-0.002760	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	10	-8.119999	-0.002165	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	20	-9.140000	-0.002437	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	30	-17.350000	-0.004627	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	40	-22.820000	-0.006085	PASS
N78-370 0-3800	30	60	DFT-16QAM	M	Outer_Full	NV	50	-12.120000	-0.003232	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	-30	-18.880000	-0.005008	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	-20	-16.610000	-0.004406	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	-10	-14.860000	-0.003942	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	0	-14.090000	-0.003737	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	10	-14.710000	-0.003902	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	20	-11.610000	-0.003080	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	30	-16.480000	-0.004371	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	40	-17.830000	-0.004729	PASS
N78-370 0-3800	30	60	DFT-QPSK	H	Outer_Full	NV	50	-10.940000	-0.002902	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	-30	-16.460000	-0.004366	PASS



N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	-20	-8.920000	-0.002366	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	-10	-19.020000	-0.005045	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	0	-13.130000	-0.003483	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	10	-17.570000	-0.004661	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	20	-22.080000	-0.005857	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	30	-12.370000	-0.003281	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	40	-13.570000	-0.003599	PASS
N78-370 0-3800	30	60	DFT-16QAM	H	Outer_Full	NV	50	-16.260000	-0.004313	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	-30	-9.650000	-0.002584	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	-20	-12.990000	-0.003478	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	-10	-16.489999	-0.004415	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	0	-13.870000	-0.003714	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	10	-15.150000	-0.004055	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	20	-13.550000	-0.003628	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	30	-18.520000	-0.004959	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	40	-13.510000	-0.003617	PASS
N78-370 0-3800	30	70	DFT-QPSK	L	Outer_Full	NV	50	-21.180000	-0.005671	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	-30	-15.230000	-0.004078	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	-20	-18.330000	-0.004908	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	-10	-18.130000	-0.004854	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	0	-11.900000	-0.003186	PASS



N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	10	-25.140000	-0.006731	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	20	-13.730000	-0.003676	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	30	-15.510000	-0.004153	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	40	-18.000000	-0.004819	PASS
N78-370 0-3800	30	70	DFT-16QAM	L	Outer_Full	NV	50	-14.660000	-0.003924	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	-30	-15.660000	-0.004176	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	-20	-10.870000	-0.002899	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	-10	-18.430000	-0.004915	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	0	-20.330000	-0.005421	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	10	-16.940000	-0.004517	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	20	-18.010000	-0.004803	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	30	-15.340000	-0.004091	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	40	-14.230000	-0.003795	PASS
N78-370 0-3800	30	70	DFT-QPSK	M	Outer_Full	NV	50	-20.180000	-0.005381	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	-30	-16.780000	-0.004475	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	-20	-5.760000	-0.001536	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	-10	-20.800000	-0.005547	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	0	-16.430000	-0.004381	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	10	-12.310000	-0.003283	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	20	-9.420000	-0.002512	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	30	-6.550000	-0.001747	PASS



N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	40	-21.090000	-0.005624	PASS
N78-370 0-3800	30	70	DFT-16QAM	M	Outer_Full	NV	50	-12.530000	-0.003341	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	-30	-8.430000	-0.002239	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	-20	-14.620000	-0.003883	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	-10	-12.950000	-0.003440	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	0	-19.190000	-0.005097	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	10	-13.940000	-0.003703	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	20	-21.000000	-0.005578	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	30	-16.920000	-0.004494	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	40	-12.970000	-0.003445	PASS
N78-370 0-3800	30	70	DFT-QPSK	H	Outer_Full	NV	50	-13.590000	-0.003610	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	-30	-15.650000	-0.004157	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	-20	-13.990000	-0.003716	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	-10	-10.990000	-0.002919	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	0	-6.450000	-0.001713	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	10	-13.310000	-0.003535	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	20	-14.750000	-0.003917	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	30	-12.120000	-0.003219	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	40	-9.530000	-0.002531	PASS
N78-370 0-3800	30	70	DFT-16QAM	H	Outer_Full	NV	50	-13.300000	-0.003533	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	-30	-14.680000	-0.003924	PASS



N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	-20	-14.600000	-0.003904	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	-10	-12.190000	-0.003259	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	0	-18.840000	-0.005037	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	10	-12.970000	-0.003468	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	20	-6.800000	-0.001818	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	30	-10.120000	-0.002706	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	40	-19.900000	-0.005321	PASS
N78-370 0-3800	30	80	DFT-QPSK	L	Outer_Full	NV	50	-10.480000	-0.002802	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	-30	-18.070000	-0.004832	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	-20	-17.580000	-0.004701	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	-10	-9.940000	-0.002658	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	0	-13.780000	-0.003684	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	10	-16.300000	-0.004358	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	20	-14.890000	-0.003981	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	30	-24.220000	-0.006476	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	40	-26.020000	-0.006957	PASS
N78-370 0-3800	30	80	DFT-16QAM	L	Outer_Full	NV	50	-18.850000	-0.005040	PASS
N78-370 0-3800	30	80	DFT-QPSK	M	Outer_Full	NV	-30	-19.230000	-0.005128	PASS
N78-370 0-3800	30	80	DFT-QPSK	M	Outer_Full	NV	-20	-14.210000	-0.003789	PASS
N78-370 0-3800	30	80	DFT-QPSK	M	Outer_Full	NV	-10	-13.720000	-0.003659	PASS
N78-370 0-3800	30	80	DFT-QPSK	M	Outer_Full	NV	0	-2.690000	-0.000717	PASS