




BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-1.4MHz-64QAM-26797-6RB#0



Date: 18.JUN.2023 14:16:46

Band26-1.4MHz-64QAM-26915-6RB#0




Date: 18.JUN.2023 14:26:03

Band26-1.4MHz-64QAM-27033-6RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-3MHz-QPSK-26805-15RB#0




Band26-3MHz-QPSK-26915-15RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:56:42

Band26-3MHz-QPSK-27025-15RB#0




Date: 18.JUN.2023 15:04:07



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03

Band26-3MHz-16QAM-26805-15RB#0




Date: 18.JUN.2023 15:05:12

Band26-3MHz-16QAM-26915-15RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:56:30

Band26-3MHz-16QAM-27025-15RB#0




Date: 18.JUN.2023 15:03:58



BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-3MHz-64QAM-26805-15RB#0



Date: 18.JUN.2023 15:05:02

Band26-3MHz-64QAM-26915-15RB#0



Date: 18.JUN.2023 14:56:22

Band26-3MHz-64QAM-27025-15RB#0

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:03:36

Band26-5MHz-QPSK-26815-25RB#0




Date: 18.JUN.2023 15:05:55

Band26-5MHz-QPSK-26915-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:12:39

Band26-5MHz-QPSK-27015-25RB#0



Date: 18.JUN.2023 15:14:29

Band26-5MHz-16QAM-26815-25RB#0

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:06:10

Band26-5MHz-16QAM-26915-25RB#0




Date: 18.JUN.2023 15:12:48

Band26-5MHz-16QAM-27015-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:14:21

Band26-5MHz-64QAM-26815-25RB#0




Date: 18.JUN.2023 15:06:18

Band26-5MHz-64QAM-26915-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:12:59

Band26-5MHz-64QAM-27015-25RB#0




Date: 18.JUN.2023 15:14:12



BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-10MHz-QPSK-26840-50RB#0



Date: 18.JUN.2023 15:21:39

Band26-10MHz-QPSK-26915-50RB#0




Date: 18.JUN.2023 15:23:48



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03

Band26-10MHz-QPSK-26990-50RB#0




Date: 18.JUN.2023 15:29:57

Band26-10MHz-16QAM-26840-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:21:51

Band26-10MHz-16QAM-26915-50RB#0




Date: 18.JUN.2023 15:23:39

Band26-10MHz-16QAM-26990-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:30:06

Band26-10MHz-64QAM-26840-50RB#0




Date: 18.JUN.2023 15:22:02

Band26-10MHz-64QAM-26915-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:23:31

Band26-10MHz-64QAM-26990-50RB#0




Date: 18.JUN.2023 15:30:14

Band26-15MHz-QPSK-26865-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:32:48

Band26-15MHz-QPSK-26915-75RB#0




Date: 18.JUN.2023 15:39:29

Band26-15MHz-QPSK-26965-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:41:26

Band26-15MHz-16QAM-26865-75RB#0




Date: 18.JUN.2023 15:32:38

Band26-15MHz-16QAM-26915-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:39:41

Band26-15MHz-16QAM-26965-75RB#0




Date: 18.JUN.2023 15:41:18

Band26-15MHz-64QAM-26865-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:32:27

Band26-15MHz-64QAM-26915-75RB#0




Date: 18.JUN.2023 15:39:49

Band26-15MHz-64QAM-26965-75RB#0



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:41:09


26dB Bandwidth

Band26-1.4MHz-QPSK-26797-6RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:15:10

Band26-1.4MHz-QPSK-26915-6RB#0




Date: 18.JUN.2023 14:26:56



BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-1.4MHz-QPSK-27033-6RB#0



Date: 18.JUN.2023 14:27:42

Band26-1.4MHz-16QAM-26797-6RB#0



Date: 18.JUN.2023 14:14:52

Band26-1.4MHz-16QAM-26915-6RB#0

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:26:46

Band26-1.4MHz-16QAM-27033-6RB#0




Date: 18.JUN.2023 14:27:34

Band26-1.4MHz-64QAM-26797-6RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:14:35

Band26-1.4MHz-64QAM-26915-6RB#0




Date: 18.JUN.2023 14:27:05

Band26-1.4MHz-64QAM-27033-6RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:27:26

Band26-3MHz-QPSK-26805-15RB#0




Date: 18.JUN.2023 14:55:34

Band26-3MHz-QPSK-26915-15RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:55:51

Band26-3MHz-QPSK-27025-15RB#0




Date: 18.JUN.2023 15:04:17

Band26-3MHz-16QAM-26805-15RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:55:24

Band26-3MHz-16QAM-26915-15RB#0




Date: 18.JUN.2023 14:56:03

Band26-3MHz-16QAM-27025-15RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:04:27

Band26-3MHz-64QAM-26805-15RB#0




Date: 18.JUN.2023 14:55:14



BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-3MHz-64QAM-26915-15RB#0



Date: 18.JUN.2023 14:56:11

Band26-3MHz-64QAM-27025-15RB#0



Date: 18.JUN.2023 15:04:35

Band26-5MHz-QPSK-26815-25RB#0

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:06:49

Band26-5MHz-QPSK-26915-25RB#0



Date: 18.JUN.2023 15:13:25

Band26-5MHz-QPSK-27015-25RB#0

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:13:43

Band26-5MHz-16QAM-26815-25RB#0




Date: 18.JUN.2023 15:06:42

Band26-5MHz-16QAM-26915-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:13:18

Band26-5MHz-16QAM-27015-25RB#0




Date: 18.JUN.2023 15:13:52

Band26-5MHz-64QAM-26815-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:06:35

Band26-5MHz-64QAM-26915-25RB#0




Date: 18.JUN.2023 15:13:08

Band26-5MHz-64QAM-27015-25RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:14:00

Band26-10MHz-QPSK-26840-50RB#0




Date: 18.JUN.2023 15:22:40

Band26-10MHz-QPSK-26915-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:23:05

Band26-10MHz-QPSK-26990-50RB#0




Date: 18.JUN.2023 15:30:49

Band26-10MHz-16QAM-26840-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:22:31

Band26-10MHz-16QAM-26915-50RB#0




Date: 18.JUN.2023 15:23:13

Band26-10MHz-16QAM-26990-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:30:30

Band26-10MHz-64QAM-26840-50RB#0




Date: 18.JUN.2023 15:22:20

Band26-10MHz-64QAM-26915-50RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:23:22

Band26-10MHz-64QAM-26990-50RB#0




Date: 18.JUN.2023 15:30:23

Band26-15MHz-QPSK-26865-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:31:49

Band26-15MHz-QPSK-26915-75RB#0




Date: 18.JUN.2023 15:40:18



BUREAU
VERITAS


Test Report No.: PSU-QSU2306120115RF03

Band26-15MHz-QPSK-26965-75RB#0



Date: 18.JUN.2023 15:40:41

Band26-15MHz-16QAM-26865-75RB#0




Date: 18.JUN.2023 15:32:04

Band26-15MHz-16QAM-26915-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:40:10

Band26-15MHz-16QAM-26965-75RB#0




Date: 18.JUN.2023 15:40:50

Band26-15MHz-64QAM-26865-75RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-15MHz-64QAM-26915-75RB#0




Band26-15MHz-64QAM-26965-75RB#0



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:40:58



BAND EDGE

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dBm)	Verdict
Band26	1.4MHz	QPSK	26797	1RB#0	-21.33	PASS
Band26	1.4MHz	QPSK	26797	6RB#0	-31.13	PASS
Band26	1.4MHz	QPSK	27033	1RB#5	-23.54	PASS
Band26	1.4MHz	QPSK	27033	6RB#0	-32.73	PASS
Band26	1.4MHz	16QAM	26797	1RB#0	-24.00	PASS
Band26	1.4MHz	16QAM	26797	6RB#0	-31.98	PASS
Band26	1.4MHz	16QAM	27033	1RB#5	-26.02	PASS
Band26	1.4MHz	16QAM	27033	6RB#0	-32.62	PASS
Band26	1.4MHz	64QAM	26797	1RB#0	-28.13	PASS
Band26	1.4MHz	64QAM	26797	6RB#0	-33.69	PASS
Band26	1.4MHz	64QAM	27033	1RB#5	-29.75	PASS
Band26	1.4MHz	64QAM	27033	6RB#0	-35.69	PASS
Band26	3MHz	QPSK	26805	1RB#0	-22.87	PASS
Band26	3MHz	QPSK	26805	15RB#0	-32.77	PASS
Band26	3MHz	QPSK	27025	1RB#14	-21.96	PASS
Band26	3MHz	QPSK	27025	15RB#0	-34.79	PASS
Band26	3MHz	16QAM	26805	1RB#0	-23.63	PASS
Band26	3MHz	16QAM	26805	15RB#0	-33.48	PASS
Band26	3MHz	16QAM	27025	1RB#14	-25.82	PASS
Band26	3MHz	16QAM	27025	15RB#0	-35.31	PASS
Band26	3MHz	64QAM	26805	1RB#0	-27.77	PASS
Band26	3MHz	64QAM	26805	15RB#0	-37.03	PASS
Band26	3MHz	64QAM	27025	1RB#14	-30.71	PASS
Band26	3MHz	64QAM	27025	15RB#0	-37.38	PASS
Band26	5MHz	QPSK	26815	1RB#0	-29.79	PASS
Band26	5MHz	QPSK	26815	25RB#0	-34.62	PASS
Band26	5MHz	QPSK	27015	1RB#24	-30.62	PASS
Band26	5MHz	QPSK	27015	25RB#0	-36.23	PASS
Band26	5MHz	16QAM	26815	1RB#0	-30.15	PASS
Band26	5MHz	16QAM	26815	25RB#0	-36.47	PASS
Band26	5MHz	16QAM	27015	1RB#24	-31.00	PASS
Band26	5MHz	16QAM	27015	25RB#0	-37.81	PASS
Band26	5MHz	64QAM	26815	1RB#0	-29.80	PASS
Band26	5MHz	64QAM	26815	25RB#0	-38.38	PASS
Band26	5MHz	64QAM	27015	1RB#24	-31.86	PASS
Band26	5MHz	64QAM	27015	25RB#0	-39.16	PASS
Band26	10MHz	QPSK	26840	1RB#0	-37.68	PASS
Band26	10MHz	QPSK	26840	50RB#0	-37.48	PASS
Band26	10MHz	QPSK	26990	1RB#49	-39.17	PASS
Band26	10MHz	QPSK	26990	50RB#0	-38.86	PASS
Band26	10MHz	16QAM	26840	1RB#0	-38.86	PASS
Band26	10MHz	16QAM	26840	50RB#0	-38.74	PASS
Band26	10MHz	16QAM	26990	1RB#49	-40.25	PASS
Band26	10MHz	16QAM	26990	50RB#0	-39.64	PASS
Band26	10MHz	64QAM	26840	1RB#0	-40.45	PASS



Test Report No.: PSU-QSU2306120115RF03

Band26	10MHz	64QAM	26840	50RB#0	-40.44	PASS
Band26	10MHz	64QAM	26990	1RB#49	-42.17	PASS
Band26	10MHz	64QAM	26990	50RB#0	-39.94	PASS
Band26	15MHz	QPSK	26865	1RB#0	-38.06	PASS
Band26	15MHz	QPSK	26865	75RB#0	-35.76	PASS
Band26	15MHz	QPSK	26965	1RB#74	-38.66	PASS
Band26	15MHz	QPSK	26965	75RB#0	-36.38	PASS
Band26	15MHz	16QAM	26865	1RB#0	-38.96	PASS
Band26	15MHz	16QAM	26865	75RB#0	-37.96	PASS
Band26	15MHz	16QAM	26965	1RB#74	-39.31	PASS
Band26	15MHz	16QAM	26965	75RB#0	-38.31	PASS
Band26	15MHz	64QAM	26865	1RB#0	-40.31	PASS
Band26	15MHz	64QAM	26865	75RB#0	-39.81	PASS
Band26	15MHz	64QAM	26965	1RB#74	-41.28	PASS
Band26	15MHz	64QAM	26965	75RB#0	-38.38	PASS


Test Graphs

Band26-1.4MHz-QPSK-26797-1RB#0



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-1.4MHz-QPSK-26797-6RB#0




Band26-1.4MHz-QPSK-27033-1RB#5




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:36:29

Band26-1.4MHz-QPSK-27033-6RB#0



Date: 18.JUN.2023 16:35:55

Band26-1.4MHz-16QAM-26797-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:39:21

Band26-1.4MHz-16QAM-26797-6RB#0




Date: 18.JUN.2023 16:41:16

Band26-1.4MHz-16QAM-27033-1RB#5




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:37:07

Band26-1.4MHz-16QAM-27033-6RB#0



Date: 18.JUN.2023 16:35:22

Band26-1.4MHz-64QAM-26797-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:38:50

Band26-1.4MHz-64QAM-26797-6RB#0




Date: 18.JUN.2023 16:42:02

Band26-1.4MHz-64QAM-27033-1RB#5




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:37:43

Band26-1.4MHz-64QAM-27033-6RB#0




Date: 18.JUN.2023 16:34:38

Band26-3MHz-QPSK-26805-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:21:27

Band26-3MHz-QPSK-26805-15RB#0




Date: 18.JUN.2023 16:20:57

Band26-3MHz-QPSK-27025-1RB#14




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:24:57

Band26-3MHz-QPSK-27025-15RB#0




Date: 18.JUN.2023 16:25:31

Band26-3MHz-16QAM-26805-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:21:56

Band26-3MHz-16QAM-26805-15RB#0




Date: 18.JUN.2023 16:20:17

Band26-3MHz-16QAM-27025-1RB#14




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-3MHz-16QAM-27025-15RB#0




Band26-3MHz-64QAM-26805-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:22:29

Band26-3MHz-64QAM-26805-15RB#0




Date: 18.JUN.2023 16:19:30

Band26-3MHz-64QAM-27025-1RB#14




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-3MHz-64QAM-27025-15RB#0




Band26-5MHz-QPSK-26815-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-5MHz-QPSK-26815-25RB#0




Band26-5MHz-QPSK-27015-1RB#24




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-5MHz-QPSK-27015-25RB#0




Band26-5MHz-16QAM-26815-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 17:00:08

Band26-5MHz-16QAM-26815-25RB#0




Date: 18.JUN.2023 16:58:45

Band26-5MHz-16QAM-27015-1RB#24




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 17:02:09

Band26-5MHz-16QAM-27015-25RB#0




Date: 18.JUN.2023 17:03:49

Band26-5MHz-64QAM-26815-1RB#0



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 17:00:35

Band26-5MHz-64QAM-26815-25RB#0




Date: 18.JUN.2023 16:58:08

Band26-5MHz-64QAM-27015-1RB#24




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 17:01:35

Band26-5MHz-64QAM-27015-25RB#0




Date: 18.JUN.2023 17:04:23

Band26-10MHz-QPSK-26840-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:04:24

Band26-10MHz-QPSK-26840-50RB#0




Date: 18.JUN.2023 16:03:54

Band26-10MHz-QPSK-26990-1RB#49




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:08:05

Band26-10MHz-QPSK-26990-50RB#0




Date: 18.JUN.2023 16:08:40

Band26-10MHz-16QAM-26840-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:04:54

Band26-10MHz-16QAM-26840-50RB#0




Date: 18.JUN.2023 16:03:16

Band26-10MHz-16QAM-26990-1RB#49




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:07:31

Band26-10MHz-16QAM-26990-50RB#0




Date: 18.JUN.2023 16:09:16

Band26-10MHz-64QAM-26840-1RB#0



BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-10MHz-64QAM-26840-50RB#0




Band26-10MHz-64QAM-26990-1RB#49




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 16:06:52

Band26-10MHz-64QAM-26990-50RB#0




Date: 18.JUN.2023 16:09:52

Band26-15MHz-QPSK-26865-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:59:24

Band26-15MHz-QPSK-26865-75RB#0




Date: 18.JUN.2023 15:59:56

Band26-15MHz-QPSK-26965-1RB#74




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:48:11

Band26-15MHz-QPSK-26965-75RB#0




Date: 18.JUN.2023 15:48:44

Band26-15MHz-16QAM-26865-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:58:52

Band26-15MHz-16QAM-26865-75RB#0




Date: 18.JUN.2023 17:07:32

Band26-15MHz-16QAM-26965-1RB#74




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:47:34

Band26-15MHz-16QAM-26965-75RB#0




Date: 18.JUN.2023 15:49:21

Band26-15MHz-64QAM-26865-1RB#0




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:58:20

Band26-15MHz-64QAM-26865-75RB#0




Date: 18.JUN.2023 16:00:58

Band26-15MHz-64QAM-26965-1RB#74




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:46:46

Band26-15MHz-64QAM-26965-75RB#0



Date: 18.JUN.2023 17:08:50

CONDUCTED SPURIOUS EMISSION

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Frequency Range	Result (dBm)	Verdict
Band26	1.4MHz	QPSK	26797	1RB#0	Range:30~9000MHz	-46.40	PASS
Band26	1.4MHz	QPSK	26915	1RB#0	Range:30~9000MHz	-46.57	PASS
Band26	1.4MHz	QPSK	27033	1RB#0	Range:30~9000MHz	-45.61	PASS
Band26	3MHz	QPSK	26805	1RB#0	Range:30~9000MHz	-45.95	PASS
Band26	3MHz	QPSK	26915	1RB#0	Range:30~9000MHz	-46.36	PASS
Band26	3MHz	QPSK	27025	1RB#0	Range:30~9000MHz	-46.53	PASS
Band26	5MHz	QPSK	26815	1RB#0	Range:30~9000MHz	-45.14	PASS
Band26	5MHz	QPSK	26915	1RB#0	Range:30~9000MHz	-44.46	PASS
Band26	5MHz	QPSK	27015	1RB#0	Range:30~9000MHz	-45.07	PASS
Band26	10MHz	QPSK	26840	1RB#0	Range:30~9000MHz	-44.44	PASS
Band26	10MHz	QPSK	26915	1RB#0	Range:30~9000MHz	-45.64	PASS
Band26	10MHz	QPSK	26990	1RB#0	Range:30~9000MHz	-46.06	PASS
Band26	15MHz	QPSK	26865	1RB#0	Range:30~9000MHz	-45.24	PASS
Band26	15MHz	QPSK	26915	1RB#0	Range:30~9000MHz	-45.95	PASS
Band26	15MHz	QPSK	26965	1RB#0	Range:30~9000MHz	-46.72	PASS
Band26	1.4MHz	16QAM	26797	1RB#0	Range:30~9000MHz	-47.17	PASS
Band26	1.4MHz	16QAM	26915	1RB#0	Range:30~9000MHz	-47.24	PASS
Band26	1.4MHz	16QAM	27033	1RB#0	Range:30~9000MHz	-47.99	PASS
Band26	3MHz	16QAM	26805	1RB#0	Range:30~9000MHz	-47.24	PASS
Band26	3MHz	16QAM	26915	1RB#0	Range:30~9000MHz	-47.65	PASS
Band26	3MHz	16QAM	27025	1RB#0	Range:30~9000MHz	-47.74	PASS
Band26	5MHz	16QAM	26815	1RB#0	Range:30~9000MHz	-46.75	PASS
Band26	5MHz	16QAM	26915	1RB#0	Range:30~9000MHz	-45.85	PASS
Band26	5MHz	16QAM	27015	1RB#0	Range:30~9000MHz	-47.76	PASS
Band26	10MHz	16QAM	26840	1RB#0	Range:30~9000MHz	-47.18	PASS
Band26	10MHz	16QAM	26915	1RB#0	Range:30~9000MHz	-48.32	PASS
Band26	10MHz	16QAM	26990	1RB#0	Range:30~9000MHz	-48.73	PASS
Band26	15MHz	16QAM	26865	1RB#0	Range:30~9000MHz	-48.53	PASS
Band26	15MHz	16QAM	26915	1RB#0	Range:30~9000MHz	-48.28	PASS
Band26	15MHz	16QAM	26965	1RB#0	Range:30~9000MHz	-47.81	PASS
Band26	1.4MHz	64QAM	26797	1RB#0	Range:30~9000MHz	-48.72	PASS
Band26	1.4MHz	64QAM	26915	1RB#0	Range:30~9000MHz	-48.78	PASS
Band26	1.4MHz	64QAM	27033	1RB#0	Range:30~9000MHz	-48.83	PASS
Band26	3MHz	64QAM	26805	1RB#0	Range:30~9000MHz	-48.19	PASS
Band26	3MHz	64QAM	26915	1RB#0	Range:30~9000MHz	-48.64	PASS
Band26	3MHz	64QAM	27025	1RB#0	Range:30~9000MHz	-48.47	PASS
Band26	5MHz	64QAM	26815	1RB#0	Range:30~9000MHz	-48.14	PASS
Band26	5MHz	64QAM	26915	1RB#0	Range:30~9000MHz	-48.84	PASS
Band26	5MHz	64QAM	27015	1RB#0	Range:30~9000MHz	-48.68	PASS
Band26	10MHz	64QAM	26840	1RB#0	Range:30~9000MHz	-48.63	PASS
Band26	10MHz	64QAM	26915	1RB#0	Range:30~9000MHz	-48.21	PASS
Band26	10MHz	64QAM	26990	1RB#0	Range:30~9000MHz	-48.76	PASS
Band26	15MHz	64QAM	26865	1RB#0	Range:30~9000MHz	-48.81	PASS
Band26	15MHz	64QAM	26915	1RB#0	Range:30~9000MHz	-48.60	PASS



Test Report No.: PSU-QSU2306120115RF03

Band26	15MHz	64QAM	26965	1RB#0	Range:30~9000MHz	-48.58	PASS
--------	-------	-------	-------	-------	------------------	--------	------


Test Graphs

Band26-1.4MHz-QPSK-26797-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 16.JUN.2023 14:21:29

Band26-1.4MHz-QPSK-26915-1RB#0-Range:30~90000MHz




Date: 16.JUN.2023 14:22:40

Band26-1.4MHz-QPSK-27033-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:32:05

Band26-3MHz-QPSK-26805-1RB#0-Range:30~90000MHz




Date: 18.JUN.2023 14:53:55

Band26-3MHz-QPSK-26915-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:57:39

Band26-3MHz-QPSK-27025-1RB#0-Range:30~90000MHz



Date: 18.JUN.2023 15:02:55

Band26-5MHz-QPSK-26815-1RB#0-Range:30~90000MHz

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:07:42

Band26-5MHz-QPSK-26915-1RB#0-Range:30~90000MHz



Date: 18.JUN.2023 15:12:20

Band26-5MHz-QPSK-27015-1RB#0-Range:30~90000MHz

Huarui 7layers High Technology
(Suzhou) Co., Ltd.


Tower N, Innovation Center, 88 Zhuyi Road,
High-tech District, Suzhou City, Anhui Province

Tel: +86 (0557) 368 1008




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:15:25

Band26-10MHz-QPSK-26840-1RB#0-Range:30~90000MHz




Date: 18.JUN.2023 15:21:08

Band26-10MHz-QPSK-26915-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:24:43

Band26-10MHz-QPSK-26990-1RB#0-Range:30~90000MHz




Date: 18.JUN.2023 15:29:33

Band26-15MHz-QPSK-26865-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 15:34:06

Band26-15MHz-QPSK-26915-1RB#0-Range:30~90000MHz




Date: 18.JUN.2023 15:39:06

Band26-15MHz-QPSK-26965-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Band26-1.4MHz-16QAM-26797-1RB#0-Range:30~90000MHz




Band26-1.4MHz-16QAM-26915-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 18.JUN.2023 14:23:38

Band26-1.4MHz-16QAM-27033-1RB#0-Range:30~90000MHz




Date: 18.JUN.2023 14:32:59

Band26-3MHz-16QAM-26805-1RB#0-Range:30~90000MHz




BUREAU
VERITAS

Test Report No.: PSU-QSU2306120115RF03



Date: 16.JUN.2023 14:53:01

Band26-3MHz-16QAM-26915-1RB#0-Range:30~90000MHz



Date: 16.JUN.2023 14:58:30

Band26-3MHz-16QAM-27025-1RB#0-Range:30~90000MHz