



5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:47:48

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:48:23

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:48:58

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:49:39

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:50:14

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:50:50


FCC Part 24E & IC RSS-133

Band 2, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:20:57

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:21:46

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:22:35

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:23:26

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:24:13

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:24:57

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:25:48

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:26:35

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:27:19

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:28:11

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:28:55







20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:29:38

FCC Part 27 & IC RSS-139

Band 4, Normal
1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:35:07

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:35:52

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:36:35

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:37:24

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:38:05

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:38:46

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:39:34

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:40:14

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:40:55

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:41:43

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:42:24

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:43:09

FCC Part 27 & IC RSS-130

Band 12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:51:52

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:52:30

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:53:07

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:53:50

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:54:27

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:55:04

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:55:45

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:56:18

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:56:53

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:57:33

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:58:06

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:58:41

FCC Part 27 & IC RSS-139

Band 66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 10:59:44

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:00:26

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:01:10

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:01:58

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 23:57:45

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:03:41

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:04:29

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:05:59

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:06:38

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:07:25

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:08:07

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:08:48

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:09:34

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:10:17

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:11:03

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:12:13

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:12:57

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602T23317E-RF Tester:Jack Zhao
Date: 15.JUN.2026 11:13:42

***** END *****