








Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn








Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn









Band4_10MHz_QPSK_20175_1RB#0_30~1000_30~10

00




Band4_10MHz_QPSK_20175_1RB#0_1000~3000_1000

~3000




Band4_10MHz_QPSK_20175_1RB#0_3000~20000_30

00~20000




Band4_10MHz_16QAM_20175_1RB#0_0.009~0.15_0.0

09~0.15



Band4_10MHz_16QAM_20175_1RB#0_0.15~30_0.15~


30



Band4_10MHz_16QAM_20175_1RB#0_30~1000_30~1

000






Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn






Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn






Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn








Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com




Hotline
 400-003-0500
 www.anbotek.com.cn







Band4_15MHz_16QAM_20175_1RB#0_1000~3000_10
00~3000



Band4_15MHz_16QAM_20175_1RB#0_3000~20000_3
000~20000




Band4_15MHz_QPSK_20325_1RB#0_0.009~0.15_0.0
09~0.15



Band4_15MHz_QPSK_20325_1RB#0_0.15~30_0.15~30





Band4_15MHz_QPSK_20325_1RB#0_30~1000_30~10
00



Band4_15MHz_QPSK_20325_1RB#0_1000~3000_1000
~3000








Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn






Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn






Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn







Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn



Appendix F: Frequency stability VS Voltage measurement

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage					
					Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band4	1.4MHz	QPSK	19957	6RB#0	VN	NT	-8.70	-0.005086	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	VL	NT	-12.46	-0.007284	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	VH	NT	-8.75	-0.005115	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	VN	NT	-6.15	-0.003595	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	VL	NT	-4.58	-0.002677	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	VH	NT	3.85	0.002251	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	VN	NT	-11.53	-0.006655	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	VL	NT	-10.70	-0.006176	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	VH	NT	-4.55	-0.002626	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	VN	NT	-7.22	-0.004167	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	VL	NT	-6.28	-0.003625	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	VH	NT	-5.34	-0.003082	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	VN	NT	-7.74	-0.004412	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	VL	NT	-14.31	-0.008157	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	VH	NT	-11.01	-0.006276	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	VN	NT	-7.37	-0.004201	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	VL	NT	-9.13	-0.005204	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	VH	NT	-5.42	-0.003090	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	VN	NT	-8.27	-0.004832	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	VL	NT	-4.49	-0.002623	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	VH	NT	-8.27	-0.004832	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	VN	NT	5.62	0.003284	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	VL	NT	-3.02	-0.001765	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	VH	NT	8.37	0.004890	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	VN	NT	-3.09	-0.001784	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	VL	NT	-4.38	-0.002528	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	VH	NT	-5.61	-0.003238	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	VN	NT	-1.82	-0.001051	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	VL	NT	3.92	0.002263	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	VH	NT	3.88	0.002240	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	VN	NT	4.11	0.002344	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	VL	NT	-9.68	-0.005520	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	VH	NT	-9.74	-0.005555	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	VN	NT	-4.41	-0.002515	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	VL	NT	5.49	0.003131	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Band4	3MHz	16QAM	20385	15RB#0	VH	NT	6.54	0.003730	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	VN	NT	-4.65	-0.002715	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	VL	NT	-8.51	-0.004969	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	VH	NT	-7.34	-0.004286	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	VN	NT	5.16	0.003013	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	VL	NT	-4.51	-0.002634	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	VH	NT	-3.98	-0.002324	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	VN	NT	-6.51	-0.003758	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	VL	NT	-5.76	-0.003325	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	VH	NT	-8.64	-0.004987	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	VN	NT	7.12	0.004110	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	VL	NT	7.41	0.004277	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	VH	NT	-5.84	-0.003371	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	VN	NT	-5.82	-0.003321	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	VL	NT	-8.98	-0.005124	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	VH	NT	-6.79	-0.003874	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	VN	NT	-4.59	-0.002619	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	VL	NT	-7.58	-0.004325	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	VH	NT	-6.57	-0.003749	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	VN	NT	-7.50	-0.004373	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	VL	NT	-7.05	-0.004111	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	VH	NT	-7.75	-0.004519	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	VN	NT	7.90	0.004560	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	VL	NT	-3.60	-0.002078	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	VH	NT	-6.77	-0.003908	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	VN	NT	4.89	0.002794	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	VL	NT	-9.24	-0.005280	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	VH	NT	-6.41	-0.003663	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	VN	NT	-8.57	-0.004990	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	VL	NT	-5.61	-0.003266	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	VH	NT	-4.68	-0.002725	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	VN	NT	4.53	0.002615	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	VL	NT	-11.14	-0.006430	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	VH	NT	-5.55	-0.003203	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	VN	NT	7.75	0.004435	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	VL	NT	-7.77	-0.004446	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	VH	NT	-6.81	-0.003897	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	VN	NT	5.76	0.003349	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	VL	NT	-5.24	-0.003047	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	VH	NT	-8.53	-0.004959	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	VN	NT	4.49	0.002592	±2.5	PASS



Band4	20MHz	QPSK	20175	100RB#0	VL	NT	-7.34	-0.004237	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	VH	NT	-4.12	-0.002378	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	VN	NT	8.01	0.004590	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	VL	NT	-5.62	-0.003221	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	VH	NT	-7.64	-0.004378	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Appendix G: Frequency stability VS Temperature measurement

Test Result

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band4	1.4MHz	QPSK	19957	6RB#0	NV	-30	-7.90	-0.004618	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	-20	-9.14	-0.005343	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	-10	-11.33	-0.006623	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	0	-7.34	-0.004291	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	10	-5.87	-0.003431	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	20	-6.98	-0.004080	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	30	-6.67	-0.003899	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	40	-4.21	-0.002461	±2.5	PASS
Band4	1.4MHz	QPSK	19957	6RB#0	NV	50	-10.83	-0.006331	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	-30	2.30	0.001344	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	-20	-4.66	-0.002724	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	-10	-6.34	-0.003706	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	0	-6.85	-0.004004	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	10	-6.05	-0.003537	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	20	-5.55	-0.003244	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	30	-8.20	-0.004793	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	40	-4.22	-0.002467	±2.5	PASS
Band4	1.4MHz	16QAM	19957	6RB#0	NV	50	-5.24	-0.003063	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	-30	-7.51	-0.004335	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	-20	-7.04	-0.004063	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	-10	-7.10	-0.004098	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	0	-10.39	-0.005997	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	10	-7.75	-0.004473	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	20	-7.58	-0.004375	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	30	-4.61	-0.002661	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	40	-5.15	-0.002973	±2.5	PASS
Band4	1.4MHz	QPSK	20175	6RB#0	NV	50	-5.51	-0.003180	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	-30	-6.79	-0.003919	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	-20	-4.71	-0.002719	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	-10	-6.90	-0.003983	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	0	-2.30	-0.001328	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	10	-6.84	-0.003948	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	20	5.59	0.003227	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	30	-4.91	-0.002834	±2.5	PASS
Band4	1.4MHz	16QAM	20175	6RB#0	NV	40	7.44	0.004294	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn



Band4	1.4MHz	16QAM	20175	6RB#0	NV	50	-4.79	-0.002765	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	-30	-9.71	-0.005535	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	-20	-10.94	-0.006236	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	-10	-9.53	-0.005432	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	0	-5.66	-0.003226	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	10	-7.90	-0.004503	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	20	-13.58	-0.007741	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	30	-7.15	-0.004076	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	40	-7.78	-0.004435	±2.5	PASS
Band4	1.4MHz	QPSK	20393	6RB#0	NV	50	-10.07	-0.005740	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	-30	-5.66	-0.003226	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	-20	-6.01	-0.003426	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	-10	-5.38	-0.003067	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	0	-5.04	-0.002873	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	10	-7.21	-0.004110	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	20	-9.61	-0.005478	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	30	-3.58	-0.002041	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	40	-8.35	-0.004760	±2.5	PASS
Band4	1.4MHz	16QAM	20393	6RB#0	NV	50	-8.80	-0.005016	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	-30	-6.78	-0.003961	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	-20	-5.51	-0.003219	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	-10	-5.59	-0.003266	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	0	3.62	0.002115	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	10	-4.18	-0.002442	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	20	-4.01	-0.002343	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	30	-3.26	-0.001905	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	40	-4.78	-0.002793	±2.5	PASS
Band4	3MHz	QPSK	19965	15RB#0	NV	50	-7.58	-0.004429	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	-30	4.81	0.002810	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	-20	6.28	0.003669	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	-10	6.74	0.003938	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	0	-5.26	-0.003073	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	10	4.43	0.002588	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	20	-4.88	-0.002851	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	30	-4.84	-0.002828	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	40	4.23	0.002472	±2.5	PASS
Band4	3MHz	16QAM	19965	15RB#0	NV	50	-6.78	-0.003961	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	-30	-7.97	-0.004600	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	-20	-6.77	-0.003908	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	-10	-5.26	-0.003036	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	0	-4.03	-0.002326	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
 Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com.cn



Band4	3MHz	QPSK	20175	15RB#0	NV	10	-3.72	-0.002147	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	20	2.05	0.001183	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	30	-5.44	-0.003140	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	40	3.78	0.002182	±2.5	PASS
Band4	3MHz	QPSK	20175	15RB#0	NV	50	9.47	0.005466	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	-30	-4.59	-0.002649	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	-20	4.65	0.002684	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	-10	2.56	0.001478	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	0	5.89	0.003400	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	10	-5.49	-0.003169	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	20	9.41	0.005431	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	30	-5.85	-0.003377	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	40	6.82	0.003937	±2.5	PASS
Band4	3MHz	16QAM	20175	15RB#0	NV	50	4.66	0.002690	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	-30	-7.10	-0.004049	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	-20	-8.55	-0.004876	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	-10	-9.27	-0.005287	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	0	-10.21	-0.005823	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	10	-10.23	-0.005834	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	20	7.95	0.004534	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	30	-8.74	-0.004984	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	40	-5.25	-0.002994	±2.5	PASS
Band4	3MHz	QPSK	20385	15RB#0	NV	50	4.43	0.002526	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	-30	5.41	0.003085	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	-20	-4.94	-0.002817	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	-10	-9.70	-0.005532	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	0	5.05	0.002880	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	10	3.89	0.002218	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	20	4.88	0.002783	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	30	4.63	0.002640	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	40	4.66	0.002658	±2.5	PASS
Band4	3MHz	16QAM	20385	15RB#0	NV	50	-3.56	-0.002030	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	-30	-6.45	-0.003766	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	-20	-5.65	-0.003299	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	-10	-4.22	-0.002464	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	0	4.25	0.002482	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	10	-7.32	-0.004274	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	20	4.12	0.002406	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	30	-3.78	-0.002207	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	40	-4.09	-0.002388	±2.5	PASS
Band4	5MHz	QPSK	19975	25RB#0	NV	50	-4.79	-0.002797	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
 Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn



Band4	5MHz	16QAM	19975	25RB#0	NV	-30	4.22	0.002464	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	-20	5.29	0.003089	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	-10	3.95	0.002307	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	0	5.45	0.003182	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	10	4.19	0.002447	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	20	5.52	0.003223	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	30	5.81	0.003393	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	40	4.66	0.002721	±2.5	PASS
Band4	5MHz	16QAM	19975	25RB#0	NV	50	5.78	0.003375	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	-30	-8.10	-0.004675	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	-20	-6.34	-0.003659	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	-10	-4.73	-0.002730	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	0	-5.49	-0.003169	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	10	6.51	0.003758	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	20	-7.25	-0.004185	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	30	-5.75	-0.003319	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	40	-3.08	-0.001778	±2.5	PASS
Band4	5MHz	QPSK	20175	25RB#0	NV	50	5.21	0.003007	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	-30	4.36	0.002517	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	-20	6.29	0.003631	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	-10	5.82	0.003359	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	0	8.63	0.004981	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	10	3.66	0.002113	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	20	-7.31	-0.004219	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	30	3.52	0.002032	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	40	-4.95	-0.002857	±2.5	PASS
Band4	5MHz	16QAM	20175	25RB#0	NV	50	4.71	0.002719	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	-30	-7.55	-0.004308	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	-20	-5.38	-0.003070	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	-10	-4.03	-0.002300	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	0	-5.29	-0.003019	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	10	-5.81	-0.003315	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	20	5.76	0.003287	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	30	-6.87	-0.003920	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	40	-7.93	-0.004525	±2.5	PASS
Band4	5MHz	QPSK	20375	25RB#0	NV	50	-5.32	-0.003036	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	-30	4.25	0.002425	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	-20	5.76	0.003287	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	-10	-4.95	-0.002825	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	0	-2.99	-0.001706	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	10	-5.81	-0.003315	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
 Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn



Band4	5MHz	16QAM	20375	25RB#0	NV	20	-2.46	-0.001404	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	30	-6.45	-0.003680	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	40	2.98	0.001700	±2.5	PASS
Band4	5MHz	16QAM	20375	25RB#0	NV	50	-4.33	-0.002471	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	-30	-6.97	-0.004064	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	-20	-8.04	-0.004688	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	-10	-4.65	-0.002711	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	0	-4.38	-0.002554	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	10	-6.34	-0.003697	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	20	-8.43	-0.004915	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	30	-4.81	-0.002805	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	40	-6.15	-0.003586	±2.5	PASS
Band4	10MHz	QPSK	20000	50RB#0	NV	50	-6.09	-0.003551	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	-30	-7.20	-0.004156	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	-20	5.97	0.003446	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	-10	-4.86	-0.002805	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	0	3.86	0.002228	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	10	-5.14	-0.002967	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	20	-5.44	-0.003140	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	30	5.36	0.003094	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	40	-5.88	-0.003394	±2.5	PASS
Band4	10MHz	QPSK	20175	50RB#0	NV	50	7.25	0.004185	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	-30	-7.52	-0.004297	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	-20	-3.82	-0.002183	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	-10	-7.95	-0.004543	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	0	-4.19	-0.002394	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	10	-6.94	-0.003966	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	20	-4.63	-0.002646	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	30	-8.30	-0.004743	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	40	-5.15	-0.002943	±2.5	PASS
Band4	10MHz	QPSK	20350	50RB#0	NV	50	-6.21	-0.003549	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	-30	-8.57	-0.004990	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	-20	-7.01	-0.004082	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	-10	-5.72	-0.003330	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	0	4.69	0.002731	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	10	-4.45	-0.002591	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	20	4.66	0.002713	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	30	-4.88	-0.002841	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	40	-3.95	-0.002300	±2.5	PASS
Band4	15MHz	QPSK	20025	75RB#0	NV	50	5.52	0.003214	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	-30	-4.66	-0.002690	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
 Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn



Band4	15MHz	QPSK	20175	75RB#0	NV	-20	9.37	0.005408	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	-10	3.33	0.001922	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	0	-4.82	-0.002782	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	10	-4.43	-0.002557	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	20	3.29	0.001899	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	30	-3.12	-0.001801	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	40	-5.71	-0.003296	±2.5	PASS
Band4	15MHz	QPSK	20175	75RB#0	NV	50	3.85	0.002222	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	-30	-6.62	-0.003788	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	-20	-4.08	-0.002335	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	-10	-3.89	-0.002226	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	0	7.41	0.004240	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	10	-4.52	-0.002587	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	20	7.44	0.004258	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	30	3.53	0.002020	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	40	-3.63	-0.002077	±2.5	PASS
Band4	15MHz	QPSK	20325	75RB#0	NV	50	-3.96	-0.002266	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	-30	-6.18	-0.003593	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	-20	-3.20	-0.001860	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	-10	-3.39	-0.001971	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	0	-5.95	-0.003459	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	10	4.76	0.002767	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	20	-7.08	-0.004116	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	30	-5.49	-0.003192	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	40	4.25	0.002471	±2.5	PASS
Band4	20MHz	QPSK	20050	100RB#0	NV	50	5.44	0.003163	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	-30	3.35	0.001934	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	-20	-4.84	-0.002794	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	-10	-4.39	-0.002534	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	0	-5.15	-0.002973	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	10	4.26	0.002459	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	20	-5.12	-0.002955	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	30	-6.47	-0.003734	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	40	-4.79	-0.002765	±2.5	PASS
Band4	20MHz	QPSK	20175	100RB#0	NV	50	3.91	0.002257	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	-30	-8.58	-0.004917	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	-20	-2.93	-0.001679	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	-10	-3.95	-0.002264	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	0	-7.32	-0.004195	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	10	-4.63	-0.002653	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	20	-11.76	-0.006739	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
 Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
 Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com.cn



Band4	20MHz	QPSK	20300	100RB#0	NV	30	3.19	0.001828	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	40	4.38	0.002510	±2.5	PASS
Band4	20MHz	QPSK	20300	100RB#0	NV	50	-4.85	-0.002779	±2.5	PASS

---END---

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.
Tel: (86) 0755-26066440 Fax: (86) 0755-26014772 Email: service@anbotek.com



Hotline
400-003-0500
www.anbotek.com.cn

