



15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:19:21

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:22:11


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:24:35


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:36:32

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:37:28

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:38:26

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:40:23

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:42:15

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Testers:Chin Qin
Date: 5.APR.2025 10:44:11

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:46:30

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:48:21

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:50:12

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:52:24

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:54:17

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 10:56:11

Band 66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:45:41

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:46:19

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:46:56

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:47:36

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:48:16

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chün Qin
Date: 4.APR.2025 09:48:54

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:50:09

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:53:38

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:56:18

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 00:58:46

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)



Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 4.APR.2025 01:01:20

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



Comment: ProjectNo.:2503R31649E-RF Tester:Chin Qin
Date: 5.APR.2025 08:58:55

Page 167 of 167