



Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:03:19

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:04:03

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:04:49

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:06:52

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:08:25

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 13:09:58

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:12:00

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:13:33

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:15:06

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:17:14

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:18:45


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12 JUN 2026 13:20:19

Band 66, Normal**1RB was the worst case****1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)**


ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:49:03

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:49:44

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:50:25

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)

ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:51:09


3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)

ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:51:50

3MHz_High_QPSK_1@0(30MHz~18.8GHz)


ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12..JUN.2026 11:52:32

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:53:15

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:53:56

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:54:37

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:56:01

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:57:24

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester: Braylon Ma
Date: 12-JUN-2026 11:58:48

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:00:14

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:01:36

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:02:59

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:04:24

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:05:47

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507A18254E-RF Tester:Braydon Ma
Date: 12..JUN.2026 12:07:09