



Band 17, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:40:12

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:40:30

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:40:47

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:42:23

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:43:15


10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:44:07


Band 38, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:46:13

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:46:37

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:47:00

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:48:46

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:49:57

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2507X37212E-RF Testers:Beydon Ma
Date: 8.NOV.2025 20:51:08


15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




20MHz_High_QPSK_1@0(30MHz~27.2GHz)




15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




15MHz_High_QPSK_1@0(30MHz~27.9GHz)




20MHz_Low_QPSK_1@0(30MHz~27.9GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




20MHz_High_QPSK_1@0(30MHz~27.9GHz)




Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:45:19

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:46:00

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:46:41

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:47:25

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:48:07

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Testers:Benyoun Ma
Date: 8.NOV.2025 18:49:27

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:51:50

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:52:31

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:53:12

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:54:09

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:55:32

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Braylon Ma
Date: 8.NOV.2025 18:56:57

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 18:59:47

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 19:01:11

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 19:02:35

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 19:04:01

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 19:05:25

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507X37212E-RF Tester: Bkaylon Ma
Date: 8.NOV.2025 19:06:53