

注1) シート状にて納入のこと。
 注2) UL-969承認ラベルのこと。
 注3) 品質特性: SS-00077「ソニー部品設計基準—機械版」の6項に定める各特性を満足すること。
 注4) この部品にはSS-00259-1に指定する物質を含んだ材料は使用してはならない。
 注5) 成形用樹脂・インキ・塗料・被覆電線はグリーンパートナー認定取引先から調達すること。
 注6) 指示なき野蠻寸は0.35mmとする。

MATERIAL STRUCTURE
 材料構成図

PCルキサン 8B35 =t0.13ラミネート
 PCルキサン 8B35 film laminate (t0.13)
 印刷面/Printing
 ポリエステルフィルム =t0.05/Polyester film(t0.05)
 アルミ蒸着/Vacuum Metallizing(Aluminium)
 アクリル系感圧性接着剤(リンテック社製 組面用)
 Acrylic pressure sensitive adhesive
 (LINTEC Co.,)
 シリコン含剥離剤/Peel paper soaked in silicon solution

116
 (76)
 68
 23
 3
 3
 3
 3
 5
 17
 0.8
 7
 7
 18
 38
 2
 R3
 33
 28
 18
 15.5
 13
 10
 3-2.5
 6-2.5
 116
 (83)
 24
 3
 4
 40

バーコード印字内容267451001

特定マーク, h=5, 清刷参照
 Special mark, h=5, Reproduction proof

SONY®
 PERSONAL COMPUTER DC 19.5V
 The Windows logo is a registered trademark of Microsoft Corporation.
 This computer is designed to operate only with genuine Sony batteries.
 Contains RD02-D110
 US: CXSMM01BRD02D110
 IC: 3652B-RD02D110
 Complies Canada ICES/NMB-003
 FCC ID: AK8PCG6J1L
 This device complies with Part 15 of the FCC Rules.
 Operation is subject to the following two conditions:
 (1) this device may not cause harmful interference,
 and (2) this device must accept any interference received,
 including interference that may cause undesired operation.
 IC: 409B-PCG6J1L

FC cUL
 RECYCLED
 1-800-822

記 載 文 字 / WRITTEN LETTER	字 高 LETTER HEIGHT	タイプフェイス / TYPE FACE
SONY®		Sony Logotype A l=22.5
MODEL	2.0	
PCG-6J1L	2.5	
PERSONAL COMPUTER DC 19.5V	2.0	NEW SONY ID TYPE HR
The Windows logo is a registered trademark of Microsoft Corporation.	1.8	
This computer is designed to operate only with genuine Sony batteries.		
Contains RD02-D110 US: CXSMM01BRD02D110 IC: 3652B-RD02D110		
Complies Canada ICES/NMB-003	1.5	NEW SONY ID TYPE HRC
I.T.E. 13C1		
FCC ID: AK8PCG6J1L	1.5	NEW SONY ID TYPE HR
This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.	1.5	NEW SONY ID TYPE HRC
IC: 409B-PCG6J1L	1.5	NEW SONY ID TYPE HR
Sony Corporation	2.0	清刷参照
MADE IN JAPAN	2.0	NEW SONY ID TYPE HR
2-674-510-XX(本図番末尾, 右上表参照のこと) (SUFFIX OF PART No., Reference on the right)	1.5	NEW SONY ID TYPE HRC