



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 29, 2003

RE: FCC ID: APYNAR0050_ATCB000471

Attention: Yoshiaki Iwasa / Yukari Ito

I have a few comments on this Application.

1. Please note that the FCC ID number on the sample label does not match the ID number in the report, 731, confidentiality request and other application documents. The report states the FCC ID is APYNAR0050 while the FCC ID sample label state it is APRNAR0050. Please correct the application documents to have the same FCC ID number. Please advise as to the proper FCC ID number.
2. Please note that your conducted data tables are not accurate. They only show compliance to the QP limits. While a device is considered compliant if the QP is under the average limit, the margin must still be compared to that which yields the least margin. For example, in the conducted data table on page 17 of the report you incorrectly show only the QP limit being met. The AV limit is only compliant by 2.8dB. In lieu of actual averaged measurements, this QP reading compared to the average limit is the margin that needs to be reported. This applies to all of your conducted data tables. Please provide a report showing the least margin in accordance with the rules.
3. Please note that much of the information on the schematics did not come through. The pin designations, chip signal names etc are blank. Perhaps this is due to Asian fonts or some other non translatable problem. Please provide readable schematics.
- 4.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.