



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 14, 2003

RE: FCC ID: APYNAR0052_ATCB000989

Attention: Naoki Sakamoto / Yukari Ito

I have a few comments on this Application.

1. Please note that 2.1033 states that the block diagram must contain crystal and clock frequency information. Please provide a block diagram in accordance with 2.1033
2. Please note that there are 3 pages to the schematics for this device. Please note that the third page is empty and the second page schematics has the bottom section cut off. Also, when magnified, the schematics are not easily readable. Please provide schematics that are easily readable and that are all there and not cut off.
3. Please note that the analyzer setting and information on the first 2 plots on page 27 and the second plot on page 28 are unreadable. Please provide plots that are easily read.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.