

MX-1000 /DocuPrint P8 BLOCK DIAGRAM

(note)

*APC : Auto Power Control

*BD : Beam Detector

*PS : Power Supply

*ICU : I/F Control Unit

*PE : Paper Empty Sensor

*Pin : Paper In Sensor

*Pout : Paper Out Sensor

