



捷聯電子股份有限公司

Top Victory Electronics (Taiwan) Co., Ltd.

18F, No. 738, Chung-Cheng Rd., Chung-Ho, Taipei Hsien, Taiwan 臺北縣中和市中正路738號18樓 TEL: 886-2-82261668 FAX: 886-2-82261666

Letter of Modification

Date: January 16, 2002

Subject : RFI related modifications incorporated into unit with [FCC ID. : ARSLM562H](#)

Dear Sir,

This letter services as our declaration that all modifications listed below are implemented in the sample submitted for pre-grant testing. We further declare that the same modifications will be implemented into all production unit to enhance compliance of the unit to FCC limits.

The modifications include the following :

1. Added 2pcs ferrite cores on the D-Sub signal cable.
@ Refer to Figure 1. (Page 7)
2. Added 2pcs ferrite cores on the DVI signal cable.
@ Refer to Figure 1. (Page 7)
3. Added a ferrite core on the DC power cord of Audio Base.
@ Refer to Figure 8. (Page 10)
4. Added a ferrite core on the cable of OSD control board.
@ Refer to Figure 25. (Page 19)
5. Added a ferrite core on the LVDS cable of LCD Panel.
@ Refer to Figure 27. (Page 20)

If you have any questions or require any other information please do not hesitate to contact our agent.

Sincerely Yours,

A handwritten signature in cursive script, reading 'George Wang', is written over a horizontal line.

George Wang
Manager

Top Victory Electronics (Taiwan) Co., Ltd.