



LG Electronics USA

1000 Sylvan Avenue Englewood Cliffs, New Jersey, United States

Date: **2014-12-10**

Manufacturer	: LG Electronics Inc.
Type of Product	: MIB2 Entry
Model Name	: MIB2
ADD Model Name	: L40VW2, L40VW2-R77N, L40VW2-R71N, L40VW2-R72N, L40VW2-C97R, L40VW2-C98R, L40VW2-C91N, L40VW2-C92N, L42VW2, L42VW2-R77N, L42VW2-R71N, L42VW2-R72N, L41VW2-C94R, L41VW2, L41VW2-C98R, L41VW2-C91N, L41VW2-C95N, L41VW2-C97R, L53VW2, L53VW2-R77N, L53VW2-R71N, L53VW2-R72N, L53VW2-C97R, L53VW2-C98R, L53VW2-C91N, L53VW2-C92N, L40SK2, L40SK2-R97N, L40SK2-R98N, L40SK2-R94N, L40SK2-R96N, L41SK2, L41SK2-R97N, L41SK2-R97M, L41SK2-R98N, L41SK2-R98M, L41SK2-R94N, L41SK2-R96N, L52SK2, L52SK2-R97N, L52SK2-R98N, L52SK2-R94N, L52SK2-R96N, L40SE2, L40SE2-R77G, L40SE2-R78G, L40SE2-R74G, L40SE2-R76G, L40SE2-R97H, L40SE2-R97D, L40SE2-R98H, L40SE2-R98D



MIB2's model name will be derivate by function accordance following table shown below

Model Name			Feature								
			SD	Aux	USB	CD	BT	DAB	RVC	CB	ML
MIB2	L40VW2	L40VW2-R77N	x	B	x		x			x	
		L40VW2-R71N	x	B							
		L40VW2-R72N	x	B				x			
		L40VW2-C97R	x	B	x	x	x		x	x	
		L40VW2-C98R	x	B	x	x	x	x	x	x	
		L40VW2-C91N	x	B		x					
		L40VW2-C92N	x	B		x		x			
	L42VW2	L42VW2-R77N	x	B	x		x			x	
		L42VW2-R71N	x	B							
		L42VW2-R72N	x	B				x			
	L41VW2	L41VW2-C94R	x	B	x	x	x			x	
		L41VW2-C98R	x	B	x	x	x	x		x	
		L41VW2-C91N	x	B		x					
		L41VW2-C95N	x	B		x		x			
		L41VW2-C97R	x	B	x	x	x		x		
	L53VW2	L53VW2-R77N	x	B	x		x			x	
		L53VW2-R71N	x	B							
		L53VW2-R72N	x	B				x			
		L53VW2-C97R	x	B	x	x	x			x	
		L53VW2-C98R	x	B	x	x	x	x		x	
		L53VW2-C91N	x	B		x					
		L53VW2-C92N	x	B		x		x			
	L40SK2	L40SK2-R97N	x	Q	x		x		x		
		L40SK2-R98N	x	Q	x		x	x	x		
		L40SK2-R94N	x	Q	x						
		L40SK2-R96N	x	Q	x			x			
	L41SK2	L41SK2-R97N	x	Q	x		x				
		L41SK2-R97M	x	Q	x		x				x
		L41SK2-R98N	x	Q	x		x	x			
		L41SK2-R98M	x	Q	x		x	x			x
		L41SK2-R94N	x	Q	x						
		L41SK2-R96N	x	Q	x			x			
	L52SK2	L52SK2-R97N	x	Q	x		x				
		L52SK2-R98N	x	Q	x		x	x			
		L52SK2-R94N	x	Q	x						
		L52SK2-R96N	x	Q	x			x			
	L40SE2	L40SE2-R77G	x	Q	x		x				
		L40SE2-R78G	x	Q	x		x	x			
		L40SE2-R74G	x	Q	x						
		L40SE2-R76G	x	Q	x			x			
		L40SE2-R97H	x	Q	x		x				
		L40SE2-R97D	x	Q	x		x				
		L40SE2-R98H	x	Q	x		x	x			
	L40SE2-R98D	x	Q	x		x	x				





Change List of L52SK2



- Delete RVC function
- Front PCB Layout

Reason for changing – PCB pattern design that only changed required from Buyer.

Before



After



Sincerely Yours,

Jacob Cho
Manager