



Intertek Testing Services

ETL SEMKO

Report No.: 0108005

Tested By: Ben, Report No.: 0108005

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0108005

Tested By: Ben, Report No.: 0108005

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.45000	31.9	48.0
0.61000	28.8	48.0
0.76500	26.5	48.0
1.00000	23.4	48.0
1.29500	19.5	48.0
11.32000	20.4	48.0

* limit

Ctrl No.: N/A