




This view of the Model 588 shows the location of the warning label as required by FCC Part 15 Doc Section 15.121 (f). The label reads as follows and the sample is provided in the label sample file.

**WARNING: MODIFICATION OF THIS DEVICE TO
RECEIVE RADIOTELEPHONE SERVICE SIGNALS IS
PROHIBITED UNDER FCC RULES AND FEDERAL LAW.**

REAR PANEL MODEL 588 93757 10/31/06 PO# XXXXX



MODEL 588

KEY TX EN TX OUT


ACC 1

ACC 2

REM
POD

DC IN

SERIAL




FUSE 25A

ETHERNET

FCC ID DJ7-588 This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

TEN-TEC, INC.
SEVIERVILLE, TN
MADE IN USA
WWW.TENTEC.COM



ANT 1

ANT 2

AUX RX



This document provides a view of the rear panel of the radio. This drawing is black on white. The actual rear panel will be painted black with white lettering. The FCC ID and compliance statement will be on a label with a permanent adhesive. The label will be black with white lettering. The location is shown above. See the label sample file for the actual look and size of label.