

Report No.: 03/3344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

(Oven)

7/2

REF .0 dBm

AT 10 dB

MKR 5.74 kHz


-26.73 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: Kenrick Wong

Date: 15/10/03

Checked By: Anthony Chan

Date: 23/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 kHz

VBW 1 kHz

STOP 13.56700 MHz

#SWP 1.00 sec

Report No.: 0313344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

(Left Front Burner)

1/1

REF 10.0 dBm

AT 20 dB

MKA 5.78 KHz


-29.85 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: KL
(Kornel Wong)

Date: 15/10/03

Checked By: [Signature]
(Anthony Chan)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 KHz

VBW 1 KHz

STOP 13.56700 MHz

#SWP 1.00 sec

Report No.: 0313344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

MKA 5.81 KHz

(left Back stove)

REF 10.0 dBm

AT 20 dB


-29.42 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: *[Signature]*
(Kerak Wong)

Date: 15/10/03

Checked By: *[Signature]*
(Anthony Chan)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 KHz

VBW 1 KHz

STOP 13.56700 MHz

#SWP 1.00 sec

Report No.: 0313344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

(Grill)

MKA 5.81 KHz


REF -20.0 dBm

AT 10 dB

-29.65 dB

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By: *[Signature]*
(Kenneth Wong)

Date: 15/10/03

Checked By: *[Signature]*
(Anthony Chen)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 KHz

VBW 1 KHz

STOP 13.55700 MHz

#SWP 1.00 sec

Report No.: 0313344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15. 225 Emissions Requirement

MKA 5.66 KHz

-29.20 dB

(Right front Burner)

REF 10.0 dBm


AT 20 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: *[Signature]*
(Kenneth Luby)

Date: 15/10/03

Checked By: *[Signature]*
(Anthony Chen)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 KHz

VBW 1 KHz

STOP 13.56700 MHz

#SWP 1.00 sec

Report No.: 03/3344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

typ

MKA 5.85 kHz

(Right Back stove)

REF 10.0 dBm

AT 20 dB

-29.20 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By: [Signature]
(Karl Wong)

Date: 15/10/03

Checked By: [Signature]
(Anthony Chan)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 kHz

VBW 1 kHz

STOP 13.56700 MHz

#SWP 1.00 sec

Report No.: 03/3344
Model No.: BE-188

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

MKR 5.61 KHz

(Microwave Oven)

REF .0 dBm

AT 10 dB


-29.34 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: KK
(Kenneth Wong)

Date: 15/10/03

Checked By: ADH
(Anthony Chan)

Date: 22/10/03

Test Result: Pass / Fail / NA

START 13.55300 MHz

#RES BW 1.0 KHz

VBW 1 KHz

STOP 13.56700 MHz

#SWP 1.00 sec