

SPORTON International Inc.


TEL : 886-2-696-2468

FAX : 886-2-696-2255

FCC TEST REPORT

REPORT NO. : F850101

SIDE VIEW



APPLICANT : D-LINK CORPORATION
EQUIPMENT : FAST ETHERNET CARD

FCC ID : KA2APC500E1
ISSUED DATE : MAY. 08, 1998
PAGE NUMBER : 15 OF 22

SPORTON International Inc.

TEL : 886-2-696-2468

FAX : 886-2-696-2255

FCC TEST REPORT


REPORT NO. : F850101

5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

FRONT VIEW



REAR VIEW



APPLICANT : D-LINK CORPORATION
EQUIPMENT : FAST ETHERNET CARD

F C C I D : KA2APC500E1
ISSUED DATE : MAY. 08, 1998
PAGE NUMBER : 14 OF 22

SPORTON International Inc.

TEL : 886-2-696-2468

FAX : 886-2-696-2255

FCC TEST REPORT


REPORT NO. : F850101

6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

FRONT VIEW



REAR VIEW



APPLICANT : D-LINK CORPORATION
EQUIPMENT : FAST ETHERNET CARD

F C C I D : KA2APC500E1
ISSUED DATE : MAY. 08, 1998
PAGE NUMBER : 20 OF 22