

Label & Label Location

Phonak Naida Link CROS



Figure 1:
Brand labeling "Phonak" on the side of the products.

Label & Label Location

Figure 2: Placement of the FCC certification number in User Guide:

This user guide is valid for:		The wireless model listed on page 2 is certified under:	
Wireless models	CE mark applied	Phonak Naída Link CROS	
Phonak Naída Link CROS	2017	USA	FCC ID: KWC-NLCROS
		Canada	IC: 2262A-NLCROS

① This user guide only applies to the CROS device. Please see the AB Naída CI sound processor user guide for instructions related to the AB Naída CI sound processor.



Notice 1:

This device complies with Part 15 of the FCC Rules and with RSS-210 of Industry Canada. Operation is subject to the following two conditions:

- 1) this device may not cause harmful interference, and
- 2) this device must accept any interference received, including interference that may cause undesired operation.

Notice 2:

Changes or modifications made to this device not expressly approved by Sonova AG may void the FCC authorization to operate this device.

Notice 3:

This device has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules and ICES-003 of Industry Canada. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This device generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful

interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this device does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the device and receiver.
- Connect the device into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.