




Note:

1. All resistance values are indicated in "ohm".
(Molten-1,000ohm, Kohn-1,000 ohm)
2. All capacitance values are indicated in "pF".
(100pF=1,000ohm, 1ohm=100pF)

ARTIN Industrial Co., Ltd.	
Fig.	THREE PHASE INDUCTION MOTOR SPEED CONTROL CIR.
Size	Normal Size
A4	Scale: 1:100000
Part No.	Scale: 1:100000

24346
25 OCT 2000