


25 JUN 2004

FCC ID: L9G708006R

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

This is to certify that the label shown above will be the production label to be used on production units of model 708006. FCC ID number: L9G708006R.


Howard Kwok

Senior Project Engineer

Authorization Letter (FCC) doc

(BANKERS: THE HONG KONG AND SHANGHAI BANKING CORPORATION, HANG SENG BANK LIMITED, STANDARD CHARTERED BANK.)

San Po Kong Head Office:

2/F., Lee Sum Fty. Bldg., 21-25 Sze Mei St., SanPoKong, Kln., H.K.
Tel: (852) 2325 5215 (12 Lines) Fax: (852) 2352 3497

URL: <http://www.artin.com.hk>**Tsim Sha Tsui Office:**

Suites 1509-11, 15/F., CMG Asia Tower, The Gateway, Harbour City, Kln.
Tel: (852) 3105 0701 (8 Lines) Fax: (852) 3105 0702 (852) 2329 0886