

SMCO400 Nameplate, located on the back of the device


FIRST ALERT®

MODEL SMCO400
Single Station Smoke Alarm & Carbon Monoxide Alarm
Powered with 2 AA Batteries (Duracell MN1500/LR6 or Energizer E91). Smoke Sensitivity: 2.1%/ft. obs. ± 25%

⚠ WARNING!
CARBON MONOXIDE CANNOT BE SEEN OR SMELLED BUT CAN KILL YOU.

IF ALARM SIGNAL SOUNDS:

1. OPERATE TEST / SILENCE BUTTON.
2. CALL YOUR EMERGENCY SERVICES (FIRE DEPARTMENT OR 911).
3. IMMEDIATELY MOVE TO FRESH AIR – OUTDOORS OR BY AN OPEN DOOR / WINDOW.

ALARM WILL NOT OPERATE IF BATTERIES ARE DEAD, DISCONNECTED OR IMPROPERLY INSTALLED. REFER TO USER'S MANUAL FOR COMPLETE BATTERY REPLACEMENT LIST, INSTALLATION, OPERATING AND SAFETY INFORMATION / INSTRUCTIONS. USE ONLY BATTERIES SPECIFIED. USE OF OTHER BATTERIES MAY HAVE A DETRIMENTAL EFFECT ON PRODUCT OPERATION. CONSTANT USE AT HIGH OR LOW TEMPERATURE OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE.

IMPORTANT!
ALARM AUTOMATICALLY COMMUNICATES WITH OTHER WIRELESS INTERCONNECT ENABLED ALARMS. REFER TO USER'S MANUAL FOR MORE INFORMATION.

FCC ID: M7U-400
This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

CARBON MONOXIDE SENSITIVITY

CO LEVEL (PPM)	70	150	400
RESPONSE TIME (MIN)	60 - 240	10 - 50	4 - 15

MAINTENANCE:
Gently vacuum or use clean compressed air to remove accumulated dust monthly. Never use water, cleaners or solvents, since they may damage the unit. Press the test button after installation, weekly and after cleaning to check all alarm functions.

ALARM GUIDE:

3 Beeps – Smoke Alarm
4 Beeps – CO Alarm

1 "Chirp" per Minute – Replace Battery
3 "Chirps" per Minute – Malfunction – Replace Alarm
5 "Chirps" per Minute – End of Life – Replace Alarm





Follow and retain user's manual
Customer Service Team: 1-800-323-9005
BRK Brands, Inc, 1301 Joe Battle
El Paso, TX 79936 USA
Made in Mexico

firstalert.com
N04-171588-177702

Manufactured PRODUCTION DATE FPO

Installed On _____
Replace By _____

REPLACE ALARM 7 YEARS AFTER INSTALLATION

