



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 30, 2005

RE: FCC ID: MBPDI010-1000_ATCB002721
Attention: Bob Cole

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the internal photos are blurred and cannot easily be viewed. Also, please note that there appears to be a covering over part of the board on the first photo. Please remove this covering and show the components/PCB layout underneath.
2. Please provide the test report for this application. Please note that based on the test report more comments and questions may arise.
3. Please provide the test setup photos for this application.
4. Please provide the manual with all appropriate FCC statements.
5. Please provide the operational description for this device.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.