

Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]
Sent: Tuesday, July 02, 2002 4:41 PM
To: kyle@celectronics.com
Subject: FCC ID: MKYMRXF102RX



Scott McCutchan.vcf

Kyle,

In order for processing of this application (FCC ID: MKYMRXF102RX) to continue, the following issue(s) will have to be addressed:

- 1) Please submit a block diagram as per FCC Part 2, Section 2.1033(b)(5).
- 2) The sample FCC Label submitted is not sufficient. It must read "FCC ID: MKYMRXF102RX", and not "FCC: MKYMRXF102RX".
- 3) According to section 4.1 of the test report, the device under test was connected to a main module and several cables were attached to its terminal blocks. On the test setup photos; however, it appears that the unit was tested as a stand alone unit. Also, under section 4.1.1, it is stated that there were no cables. Please explain.

Do not reply to this message. Please upload your response and any attachments onto our web server. Your correspondence number will be MKYMRXF102RX-1.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to scott@celectronics.com.

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Lab Manager
Compatible Electronics, Brea Division
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>

We also offer EMC Design Seminars! Click on the link below for details.

<http://www.celectronics.com/seminar.htm>