

Dear Tim,

1. Will take the photo immediately.
2. This holster does not include any RF shielding/absorbing material too.

In the mean time, please still prepare the grant or TCB confirmation letter before we upload the updated photo. Thanks again.

BR
Daniel

-----Original Message-----

From: Timothy R. Johnson [<mailto:tjohnson@atcb.com>]

Sent: Wednesday, October 25, 2006 4:02 PM

To: Daniel Lee (æ Ǥæ̃ʔa'OE)

Subject: RE: www.AmericanTCB.com ATCB004167 | MSQO2Z1 | | MSQO2Z1_ATCB004167

Daniel,

2 items on this still...

- 1) The additional expected photograph for item 2 does not appear to be provided. Looking at the last photograph of the internal photographs, a photo of the other side of that board does not appear to be provided.
- 2) While the holster may not contain metal, some holsters have been found to contain RF shielding/absorbing capability. Please explain.

Tim