



Report No.: 0012273
0102273
Talk
Mode

Tested By: Hong, Report No.: 0012273

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0012273
~~0102273~~₃₁
Talk
Mode

Tested By: Hong, Report No.: 0012273

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
29.47500	29.8	48.0

* limit exceeded

Ctrl No.: N/A