




Company Name:	<i>Samsung Telecommunications America</i>
FCC ID:	<i>NP8-1900-10-PRU</i>
Work Order Number	<i>2000034 / A0398</i>

APPENDIX D:

FREQUENCY STABILITY PLOTS




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D1: CHANNEL 1175 0C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D2: CHANNEL 1175 10C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D3: CHANNEL 1175 -10C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D4: CHANNEL 1175 20C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D5: CHANNEL 1175 -20C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D6: CHANNEL 1175 20C 132




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D7: CHANNEL 1175 20C 97




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D8: CHANNEL 1175 30C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D9: CHANNEL 1175 -30C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D10: CHANNEL 1175 40C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D11: CHANNEL 1175 50C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D12: CHANNEL 25 0C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D13: CHANNEL 25 10C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D14: CHANNEL 25 -10C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D15: CHANNEL 25 20C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D16: CHANNEL 25 -20C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D17: CHANNEL 25 20C 132




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D18: CHANNEL 25 20C 97




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D19: CHANNEL 25 30C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D20: CHANNEL 25 -30C 115




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D21: CHANNEL 25 40C 115



Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



D22: CHANNEL 25 50C 113