

INTERTEK TESTING SERVICES

Report No.: 0210752
Model No.: ML13963

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

hp

MKA 50.0 KHz

REF 97.0 dBμV

AT 10 dB

-55.0 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By: Cathy
(Cathy Tse)

Date: 3/8/2002

Checked By: [Signature]
(Ivar)

Date: 5/8

Test Result ☒ Pass / Fail / NA

START 49.8100 MHz

STOP 49.9100 MHz

#RES BW 3.0 KHz

#VBW 3 KHz

#SWP 1.50 sec