

GESTEK 98-F011

GESTEK

FCC ID: NSB9800

Report #: 97C026 F

N03, Pau-Tou-Tsuo Valley, Chia-Pau Tsuen, Lin Kou Hsiang, Taipei County, Taiwan, R.O.C. Tel:886-2-2603-5321 Fax:886-2-2603-5325

Appendix C

User Manual

Innolabs Corporation
FCC ID: NSB9800
Notebook Computer, Model 9800 Series
GTK98-F011 / May 25, 1998

INSTRUCTIONS MANUAL

FEDERAL COMMUNICATIONS COMMISSION INTERFERENCE STATEMENT

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

FCC Caution: To assure continued compliance, the user must use only shielded interface cables when connecting computer to peripheral devices. Also, any changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate this equipment.