

Proprietary IDENTEC SOLUTIONS document. Confidentiality requested for this document.

ANNEX 3 TO TEST REPORT # EMCC-010133AF, 2002-07-19

PHOTOGRAPHS OF EQUIPMENT UNDER TEST (EUT) INTERNAL VIEWS

EQUIPMENT UNDER TEST:

Trade Name:	ILR®
Model:	i-Port3
Serial No:	143
Equipment Category:	902-928 MHz Frequency Hopping Spread Spectrum Transceiver
Manufacturer:	IDENTEC SOLUTIONS AG
Address:	Millenium Park 2 A-6890 Lustenau Austria
Phone:	+43-5577-87 387-0
Fax:	+43-5577-87 387-15
E-mail:	r.gantner@identecsolutions.at

RELEVANT STANDARD: 47 CFR Part 15.247

CONTENTS

Page


1	View of the Connecting Compartment	2
2	Top View of the Internal Assembly (Top View of RF Board)	3
3	Rear View of the Internal Assembly (Rear View of IO Board)	4
4	Top View of the IO Board with Web Interface Board	5
5	Top View of IO Port, Web Interface Board Removed	6
6	Top View of the Web Interface Board	7
7	Rear View of RF Board	8

1 VIEW OF THE CONNECTING COMPARTMENT




TEST OF IDENTEC SOLUTIONS ILR® TRANSCEIVER MODEL I-PORT3 TO 47 CFR PART 15.247

2 TOP VIEW OF THE INTERNAL ASSEMBLY (TOP VIEW OF RF BOARD)




3 REAR VIEW OF THE INTERNAL ASSEMBLY (REAR VIEW OF IO BOARD)




TEST OF IDENTEC SOLUTIONS ILR® TRANSCEIVER MODEL I-PORT3 TO 47 CFR PART 15.247

4 TOP VIEW OF THE IO BOARD WITH WEB INTERFACE BOARD



5 TOP VIEW OF IO PORT, WEB INTERFACE BOARD REMOVED



TEST OF IDENTEC SOLUTIONS ILR® TRANSCEIVER MODEL I-PORT3 TO 47 CFR PART 15.247

6 TOP VIEW OF THE WEB INTERFACE BOARD



7 REAR VIEW OF RF BOARD

