

INTERTEK TESTING SERVICES

Report No.: 0512637

Model No.: 98161

hp Pursuant to FCC Part 15 Section 15. 225 Emissions Requirement

MKR -456.8 KHz

REF .0 dBm

AT 10 dB

-60.59 dB

Sample 1/1

Dress Sensor

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By: *[Signature]*
(Gary Li)

Date: 27/6/05

Checked By: *[Signature]*
(Anthony Chan)

Date: 5/7/05

Test Result: Pass / Fail / NA

START 13.1100 MHz

STOP 14.0100 MHz

#RES BW 1.0 KHz

#VBW 3 MHz

#SWP 10.0 MHz

Code M_base with plot_a / Effective Date: 15 Jul 2002

INTERTEK TESTING SERVICES

Report No.: 0512644

Model No.: 98661

hp Pursuant to FCC Part 15 Section 15. 225 Emissions Requirement

MKR -456.8 KHz Sample 1/1

REF -10.0 dBm


AT 10 dB

-63.39 dB

Mouth Sensor

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By: Gary Li

Date: 7/6/05

Checked By: Anthony Chan

Date: 6/7/05

Test Result: Pass / Fail / NA

START 13.1100 MHz

STOP 14.0100 MHz

#RES BW 1.0 KHz

#VBW 3 MHz

#SWP 5.00 sec

Code: M_bandwidth plot_a / Effective Date: 15 Jul 2002

Report No.: 0512677
Model No.: 98161

hp Pursuant to FCC Part 15 Section 15. 225 Emissions Requirement

MKR -456.8 KHz Sample 4/1

REF .0 dBm


AT 10 dB

-53.01 dB

Bottom Sensor

PEAK
LOG
10
dB/

VA SB
SC FQ
CORR



Tested By: *(Signature)*
(Gary Li)

Date: 22/6/05

Checked By: *(Signature)*
(Anthony Chan)

Date: 6/7/05

Test Result: Pass / Fail / NA

START 13.1100 MHz

STOP 14.0100 MHz

#RES BW 1.0 KHz

#VBW 3 MHz

#SWP 5.00 sec