

FCC INFORMATION

FCC ID: QUECSXCVR2

THE CYBERSYNC™ CSXCV TRANSCEIVER for EINSTEIN™

The CSXCV transceiver (transmitting receiver) is designed for second-generation Paul C. Buff, Inc.™ flash units, fitting in the CSXCV transceiver receptacle located on each unit (currently only compatible with Einstein™ E640 flash units). Such units do not contain the RJ-11 telephone-style analog remote jacks (required for use with the CSR+ and CSRB+ receivers) and the CSXCV module forms an all-digital interface from either the CST trigger transmitter or Cyber Commander™ remote control transmitter.

The CSXCV module is powered by the host light unit with frequency and channel selection also performed by the host light unit. This makes the CSXCV module truly plug-and-play, unleashing the full power and accuracy of a sophisticated all-digital remote control system.

The CSXCV receivers facilitate adjustment of flashpower and other parameters when used with the Cyber Commander™ remote control transmitter. When signaled by the CST trigger transmitter, the receivers will only serve to fire the units to which they are attached.

FCC Notice:

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference. (2) This device must accept any interference received, including interference that may cause undesired operation.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

WARNING: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.