

Company **Preco Inc.**
Model **PV2000** **(CW mode)**
Date **6/20/00**
Engineer **Clyde Shaver**

Note: Pulse mode is normal operation for this device.
CW results are not required, but are provided FYI.

FCC 15.249 Radiated Emissions

Frequency	Antenna Polarity	Reading	Antenna Factor	Cable Loss	Pre-amp	Duty Cycle	Corrected Reading	Limit	Margin
Mhz	H/V	dB(uV)	dB	dB	dB	dB	dB(uV/m)	dB(uV/m)	dB
5797.5	H	56.28	34.8	3.0	0.0	20.0	74.08	94.0	-19.92
11597.5	H	20.67	39.0	4.1	0.0	20.0	43.77	54.0	-10.23

- Note:**
1. All measurements were made at 3 meters.
 2. Negative signs (-) in the margin column signify levels below the limit.
 3. See plots on the following pages.
 4. Reading at 11597.5 Mhz was less than 20.67, see plot.

Equipment HP8593EM Spectrum Analyzer (9Khz--12.8Ghz)
 Emco Model 3115 Double-Ridged Waveguide Horn Antenna

Equipment calibration data, and certifications available upon request.