

8

7

6

5

4

3

2

1

PROPRIETARY NOTICE

NOTICE

REVISIONS

THIS DOCUMENT AND THE INFORMATION DISCLOSED HEREIN ARE PROPRIETARY DATA OF ACSS, LLC. NEITHER THIS DOCUMENT NOR THE INFORMATION CONTAINED HEREIN SHALL BE REPRODUCED, USED, OR DISCLOSED TO OTHERS WITHOUT THE WRITTEN AUTHORIZATION OF ACSS, LLC.

THIS DOCUMENT IS BEING FURNISHED IN CONFIDENCE BY ACSS, LLC THE INFORMATION DISCLOSED HEREIN FALLS WITHIN EXEMPTION (b) (4) OF 5 USC 552 AND THE PROHIBITIONS OF 18 USC 1905.

CRNO.

REV

DESCRIPTION

5241

A

SEE DESCRIPTION PER CHANGE REQUEST

07/03/02

5384

B

SEE DESCRIPTION PER CHANGE REQUEST

08/09/02

5555

C

SEE DESCRIPTION PER CHANGE REQUEST

09/09/02

5608

D

SEE DESCRIPTION PER CHANGE REQUEST

11/05/02

5787

E

SEE DESCRIPTION PER CHANGE REQUEST

01/10/03

5822

5847

5849

5854

5909

E

SEE DESCRIPTION PER CHANGE REQUEST

02/04/03

1

2

2

SELF TEST

Replace this LRU if ONLY the red TAWS P1 STATUS or TCAS Fail lamp is on during any status display (following the lamp test). When additional lamps are on, correct indicated sub-system ~~DEAD~~ to replacement of this LRU.

TAWS STATUS

TAWS FAIL

TAWS P1 STATUS

TAWS P2 STATUS

TCAS STATUS

TCAS PASS

TCAS FAIL

TA DISP

RA DISP

RAD ALT

XPDR BUS

TOP ANT

BOT ANT

PUSH TO TEST

DATA LOADER

TABLE 1

PRODUCTION END ITEM OPERATIONAL SOFTWARE/FIRMWARE CONFIGURATION TABLE

PART NUMBER	SOFTWARE								FIRMWARE		
	TCAS BOOT	TCAS OPERATIONAL	TAWS P1 BOOT	TAWS P2 BOOT	TAWS P1 DATA LOAD	TAWS P2 DATA LOAD	TAWS P1 OPERATIONAL	TAWS P2 OPERATIONAL	TAWS CPLD	TAWS FPGA A	TAWS FPGA B
9000000-55001	PS4084562-102 TT7517989-103	PS4084561-912	9000278-001	9000279-001	9000276-001	9000277-001	9000274-001	9000275-001	9000230-002	9000231-003	9000232-001

NOTES:

1.

CAUTION

ELECTROSTATIC SENSITIVE EQUIPMENT
SPECIAL HANDLING REQUIRED

THIS DEVICE IS SUBJECT TO DAMAGE BY ELECTROSTATIC CHARGES.

2.

INSTALL TO FRONT PLATE PER ITEM 701. LOCATE APPROXIMATELY AS SHOWN. TYPE APPLICABLE DASH NUMBER, SERIAL NUMBER, DATE, INSPECTOR NUMBER, WEIGHT, AND MARK APPLICABLE HARDWARE MODIFICATION LETTER ON ITEM 2.

3.

TEST PER ITEM 3 (SPEC 8000253-001).

4.

5.

THIS DRAWING DEFINES END ITEM UNIT 9000000-YYTZZ.
YY = HARDWARE CONFIGURATION 55.
T = TCAS SOFTWARE CONFIGURATION FROM 0 TO Z.
ZZ = TAWS CONFIGURATION FROM 01 TO 99.

REVISION STATUS OF PARTS LIST SHALL BE THE SAME AS THE BASIC DRAWING NUMBER. SEE SEPARATE PARTS LIST.

UNLESS OTHERWISE SPECIFIED, DIMENSIONS ARE IN INCHES: TOLERANCES: ANGLES ± - 2 PL DEC ± - 3 PL DEC ± -

THIRD ANGLE PROJECTION

INTERPRET DIMENSIONS AND TOLERANCES PER AMSE Y14.5M-1994

FOR REFERENCE

ORIGINAL C.R.

PRODUCT LINE NO.

AW/PS ANALYSIS EB

REF DWG

REF SPEC

9000000-55001

9000000-55001

NEXT ASSY

END ITEM

APPLICATION

SCALE NONE

OPERATIONAL NOTE

ACSS

Aviation Communication & Surveillance Systems
19810 North 71st Avenue
Phoenix, Arizona 85027-4400

TITLE

ASSEMBLY, T2CAS
MODEL TT-951

SIZE

CAGE CODE

DRAWING NO.

9000000-55001

REV

E

SHEET 1 OF 2

8	7	6	5	4	3	2	1
H		G		F		E	
G		F		E		D	
F		E		D		C	
E		D		C		B	
D		C		B		A	
C		B		A			
B		A					
A							

REVISIONS		
CRNO.	REV	DESCRIPTION
5241	A	SEE DESCRIPTION PER CHANGE REQUEST 08/09/02
5384	B	SEE DESCRIPTION PER CHANGE REQUEST 09/09/02
5555 5608	C	SEE DESCRIPTION PER CHANGE REQUEST 11/05/02
5787 5792	D	SEE DESCRIPTION PER CHANGE REQUEST 01/10/03
5822 5847 5849 5854 5909	E	SEE DESCRIPTION PER CHANGE REQUEST 02/04/03

T2CAS COMPUTER UNIT MODIFICATION TABLE							
AFFECTED SUBASSEMBLY		MODIFICATION NUMBER	HDWR MOD	TCAS S/W MOD	TAWS S/W MOD	REMARKS	UNIT SERIAL NUMBER EFFECTIVITY OR SOONER
PART NUMBER	REV						
7517920-904 7517925-902 9000000-55001	A H E		A			CORRECT AUDIO NOISE ON 600 OHM OUTPUT DURING TRANSMIT SEQUENCE, CORRECT RF CABLE TORQUE, SEAL AND GROUND INTEGRITY.	ALL
TT7517989-102 PS4084561-902 9000000-55001	- - E		B			INCREASES DATA LOADER COMPATIBILITY AND CHANGES FIELD PROGRAMMABLE GATE ARRAY (FPGA)	ALL
7517925-902 TT7517989-103 9000000-55001	K - E		C			ENHANCES CHANGE 7.0 TRANSPONDER INTEROPERABILITY, IMPROVES BITE PERFORMANCE AND INCORPORATES MOPS CP110 CHANGES.	ALL