



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 9, 2003

RE: SENTON Enterprises Limited

FCC ID: PEGSH50201

After a review of the submitted information, I have a few comments on the above referenced Application.

EMC Report/General:

- 1) Please correct the labeling via the email that was previously sent.
- 2) Section 3.3.1 of the test report still shows limits of 15.231. Please adjust this section of the report to list limits according to 15.249.
- 3) Section 3.5.2 of the test report shows the incorrect limit for 15.249 for the fundamental. Please correct the limit and margin given in this table. Additionally, average factors may not be applied to the fundamental under the requirements of 15.249. Please correct.
- 4) The banded emission plot specified on page 11 of the test report has not been provided.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.