



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 15, 2004

RE: Arima Communication Corp.

FCC ID: PJO2600

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative Issues:

- 1) The users manual appears to be missing information regarding body worn and spacing requirements. Please updated.
- 2) The users manual mentions GSM/GPRS. However all data appears at a crest factor of 8.3. Please explain what maximum class level this device will function at for purposes GSM/GPRS.

Technical Issues:

- 3) Please provide at least one SAR plot for each of the tilted positions in the test report.
- 4) From the test configuration photographs it can not be determined if the device had the microphone/earpiece installed during body worn SAR tests. Please explain.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.