



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 3, 2003

RE: ZIDA Technologies Ltd.

FCC ID: PRB-NET-AP11B-01

After a review of the submitted information, I have a few comments on the above referenced Application.

EMC Report/General:

- 1) The block diagram should show the frequencies of all oscillators in the TX portion of the device (CFR 2.1033(a)(5)). Please provide an updated version that includes this information.
- 2) The schematics do not appear to contain the RF portion of the circuitry. Please provide an updated set of schematics that includes this as specified by CFR 2.1033(a)(5).
- 3) The device appears to contain 3 antennas. However only 2 are used. Please explain the purpose of 3 antennas.
- 4) The device appears to contain 2 different antennas. The block diagram appears to show that the device may transmit out of either antenna, but only one set of test results have been provided. Please explain or provide additional data for the 2nd antenna.
- 5) Please provide information for both antennas (i.e., are both dipoles, are both + 1 dBi, etc.).

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.