



Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To whom it may concern:

The AeroScout Exciter (EX-3100) label is too small to include the statement as specified in FCC part 15 Sub-part A section 15.19(a)(3):

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason we used the provisions of FCC Part 15 Sub-part A Section 15.19 (a)(5) and we placed this statement in a prominent location in the users manual.

Sincerely,

Edward Mirodin
Senior RF Engineer
Aeroscout, Ltd

Signature:

A handwritten signature in blue ink, appearing to be "E. Mirodin", written over a light blue horizontal line.

Date: 06/02/2006