

INTERTEK TESTING SERVICES

Report No.: 0215010
Model No.: HK-200

Pursuant to FCC Part 15 Section 15. 217 Emissions Requirement

MKR 17.062 msec

REF 97.0 dBμV

AT 10 dB


.00 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: *[Signature]*

Date: 22-1-02

Checked By: *[Signature]*

Date: 22/1/1

Test Result: Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: 0215010
Model No.: HK-200

Pursuant to FCC Part 15 Section 15. 22 Emissions Requirement

hp


MKR 17.175 msec

REF 97.0 dBμV

AT 10 dB

-.03 dB

PEAK
LOG
10
dB



VA SB
SC FC
CORR

Tested By:

(Signature)
(Gangli)

Date: 22-11-02

Checked By:

(Signature)
(Wan)

Date:

22/11

Test Result: Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0215010
Model No.: HK-200

Pursuant to FCC Part 15 Section 15.727 Emissions Requirement


MKR 1.4250 msec

REF 97.0 dBμV

AT 10 dB

.25 dB

PEAK
LOG
10
dB



VA SB
SC FC
CORR

Tested By:

(Signature)
(Gary L. J.)

Date: 22-11-02

Checked By:

(Signature)
(Van)

Date: 22/11

Test Result: Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0215010
Model No.: HK-700

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKR 450.00 μ sec

REF 97.0 dB μ V

AT 10 dB


.39 dB

PEAK

LOG

10

dB



VA SB

SC FC

CORR

Tested By:

(Signature)
(Eager)

Date: 72-11-02

Checked By:

(Signature)
(Van)

Date:

22/11

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec