

INTERTEK TESTING SERVICES

Report No.: 0309/64
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

DLT: 16.52ms


-0.08dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 70ms

F: 49.860000MHz

Tested By: LR
(Kenneth Wong)

Date: 10/6/03

Checked By: [Signature]
([Signature])

Date: 12/6

Test Result: Pass / Fail / NA

Report No.: 0309/64
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 16.52ms

0.04dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.660000MHz

Tested By: Ken Wray

Date: 10/6/03

Checked By: [Signature]

Date: 12/6

Test Result: Pass / Fail / NA

Report No.: 0309/64
Model No.: 2340Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 1.56ms

-0.10dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.860000MHz

Tested By: LRKen WongDate: 10/6/03Checked By: TLTLDate: 12/6Test Result: Pass / Fail / NA

Report No.: 0309164
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 400us

0.00dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.860000MHz

Tested By: LR
(Kevin Wong)

Date: 10/6/03

Checked By: [Signature]
(10/6/03)

Date: 12/6

Test Result : Pass / Fail / NA